

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name NORTHEAST DRINKARD UNIT
8. Well No. 807
9. Pool name or Wildcat N. EUNICE BLINEBRY-TUBB-DRINKARD

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER INJECTOR	
2. Name of Operator Shell Western E&P Inc.	
3. Address of Operator P.O. Box 576 Houston, TX 77001-0576	
4. Well Location Unit Letter <u>G</u> : <u>1980</u> Feet From The <u>NORTH</u> Line and <u>2080</u> Feet From The <u>EAST</u> Line Section <u>22</u> Township <u>21S</u> Range <u>37E</u> NMPM LEA County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3417' KB	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: REP PKR; RESTORE MI <input checked="" type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

9-23 TO 9-30-92:

SHUT BTM VLV & TST TBG, DID NOT HOLD. REL ON/OFF TOOL & FLSHD TBG. LATCH AGAIN & TSTD TBG, DID NOT HOLD. POH W/INJ EQMT. CO W/BIT & SCRPR TO 5670', POH. SET RBP @ 5665' & PKR @ 5635'. PT RBP, WOULD NOT HOLD. LD BACKSIDE & PT TO 500# FOR 15 MIN, HELD. POH W/PKR & RBP. RIH W/INJ EQMT, SETTING GUIB UNI-VI PKR @ 5600'. PT TBG TO 500#, HELD. INHIB WELL. STUNG TBG INTO PKR & ATTEMPTD TO OPEN BHV ON PKR. WOULD NOT OPEN. POH W/TBG & PKR. REP PKR (PKR FULL OF SCALE). RIH W/INJ EQMT. RESET GUIB UNI-VI PKR @ 5600'. PT TBG TO 500#, HELD. INHIB WELL. OPEN BHV IN PKR. PT TBG/CSG ANN TO 500# FOR 30 MIN, HELD. CLN LOC. PMPD 5 BBLS 15% NEFE HCL DWN TBG FOR SCALE BU, FLSH W/20 BBLS 9# BRINE. RTI.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE J. F. N. Kelldorf TITLE TECH. MANAGER - ENVIR. ENG. DATE 10/30/92

TYPE OR PRINT NAME W. F. N. KELLDORF TELEPHONE NO. 713/870-3797

(This space for State Use)
ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT I SUPERVISOR

APPROVED BY _____ TITLE _____ DATE NOV 03 '92

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED

NOV 0 8 1992

OCD HOBBS OFFICE