

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL ☒ GAS WELL ☐ OTHER ☐	WELL API NO.
2. Name of Operator SHELL WESTERN E&P INC.	5. Indicate Type of Lease STATE ☐ FEE ☒
3. Address of Operator P. O. BOX 576, HOUSTON, TX 77001 (WCK 4435)	6. State Oil & Gas Lease No.
4. Well Location Unit Letter <u>H</u> : <u>1980</u> Feet From The <u>NORTH</u> Line and <u>660</u> Feet From The <u>EAST</u> Line Section <u>22</u> Township <u>21S</u> Range <u>37E</u> NMPM <u>LEA</u> County	7. Lease Name or Unit Agreement Name NORTHEAST DRINKARD UNIT
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3412' GR	8. Well No. 809
	9. Pool name or Wildcat NORTH EUNICE BLINEBRY-TUBB-DRINKARD OIL & GAS

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUSSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☐	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPNS. ☐	PLUG AND ABANDONMENT ☐
PULL OR ALTER CASING ☐		CASING TEST AND CEMENT JOB ☐	
OTHER: ☐		OTHER: <u>Cmt sqzd, OAP & Acid</u> ☒	

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

4-10 to 4-26-89:

POH w/prod equip. Tagged fill @ 6456'. Pres tstd CIBP @ 6466' to 1000#, held OK. Set cmt ret @ 6256'. Cmt sqzd Tubb/Drinkard perms 6356' - 6444' w/75 sx Cls "C" cmt + .3% CF-1 followed by 50 sx Cls "C" cmt + 2% CaCl₂. Set pkr @ 5396'. Sqzd Blinebry perms 5510' - 5720' w/200 sx Cls "C" cmt + .3% CF-1 followed by 50 sx Cls "C" cmt + 2% CaCl₂. Rel pkr & POH. DO cmt 5396' - 5640'. Pres tstd sqz to 500#, held OK. DO cmt to 5750'. Pres tstd sqz to 500#, held OK. Fell thru cmt @ 5760'. DO cmt ret @ 6256' & cmt to 6450'. Pres tstd sqz to 500#, held OK. Drld CIBP @ 6486'. Mld over fish (Hookwall pkr) to 6490' & rec. CO to 6615'. Perf'd Blinebry/Tubb/Drinkard 5714' - 6518' (1 JSPP). Acid perms 5714' - 6518' + Drinkard OH 6550' - 6615' w/9660 gals 15% HCl + 250# rock salt. Installed prod equip & ret'd to prod.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE J. H. SMITHERMAN TITLE REGULATORY SUPV. DATE 5-26-89
TYPE OR PRINT NAME J. H. SMITHERMAN (713) 870-3797 TELEPHONE NO.

(This space for State Use)

ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT I SUPERVISOR

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY:

MAY 31 1989