

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

2040 South Pacheco
Santa Fe, NM 87505

WELL API NO.
30-025-06734

5. Indicate Type of Lease
STATE ☐ FEE ☒

6. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS)

7. Lease Name or Unit Agreement Name

Eubank

1. Type of Well:
OIL WELL ☐ GAS WELL ☐ OTHER Shut In

2. Name of Operator
Zia Energy, Inc.

8. Well No.
8

3. Address of Operator
PO Box 2510, Hobbs, NM 88241

9. Pool name or Wildcat
Paddock

4. Well Location
Unit Letter G | 1750 Feet From The North Line and 2310 Feet From The East Line
Section 22 Township 21S Range 37E NMPM Lea County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)
3425

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>		CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER: <input type="checkbox"/>		OTHER: <input type="checkbox"/>	

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

2/8/99 GIH and set cement retainer at 5070'. Squeezed 50 sx of cement with 40# of maxiseal, sting out of retainer and dumped 25 sx on retainer. Circulated hole with salt gel mud. Cut casing at 3843'.

2/9/99 POH with 118 joints of 5 1/2" casing.

Pumped a 35 sx plug at 3900'

2/10/99 Tagged cement at 3699'. Spot 100' plug at 2850'. SI 4 hrs and tagged at 2770'. Dumped 25 sxs additional cement, bringing top to 2670'.

Pumped a 100' plug at 1200'.

Pumped a 100' plug at 365'.

Pumped 10 sx at surface.

Cut casing off 4' below surface and welded on dry hole marker.

Cut off anchors and cleaned location.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Scott Nelson TITLE Engineer DATE 2/17/99

TYPE OR PRINT NAME Scott Nelson 393-2937 TELEPHONE NO.

(This space for State Use)

APPROVED BY [Signature] TITLE [Signature] DATE [Signature]

CONDITIONS OF APPROVAL, IF ANY:

JC GWW

do