

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

OIL CONSERVATION DIVISION

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-025-06737
5. Indicate Type of Lease STATE ☐ FEE ☒
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name ARGO A
8. Well No. 5
9. Pool name or Wildcat HARE-SAN ANDRES

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE 'APPLICATION FOR PERMIT' (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL ☐ GAS WELL ☒ OTHER WATER SOURCE	
2. Name of Operator Shell Western E&P Inc.	
3. Address of Operator P.O. Box 576 Houston, TX 77001-0576 (WCK 4435)	
4. Well Location Unit Letter F : 1980 Feet From The NORTH Line and 2130 Feet From The WEST Line Section 22 Township 21S Range 37E NMPM LEA County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3427' KB	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK ☐	REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐	ALTERING CASING ☐
PULL OR ALTER CASING ☐	COMMENCE DRILLING OPNS. ☐
OTHER: ☐	PLUG AND ABANDONMENT ☐
	CASING TEST AND CEMENT JOB ☐
	OTHER: PB & RECOMPLETED TO SAN ANDRES ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

9-23 TO 10-24-90:
POH W/TBG. CO TO 6440'. SET CIBP @ 5440' & CAPPED W/35' CMT. RAN ETT, GR/CBL/CCL &
GR/CNL/CCL. PERF'D @ 3965' (4 SPF). SPOT 5 BBLs 20% HCL ACROSS PERFS. ATTEMPTD TO CIRC
175 BBLs FW, COULD NOT CIRC. CUT FLG FROM PROD CSG. FREEPOINT 5-1/2 IN. CSG @ 2756'.
POH W/B6 JTS 5-1/2 IN. 15.5# CSG. CO TO TOL @ 2756'. RIH W/1 JT 5-1/2 IN. 15.5# CSG
W/CENTRALIZED TAPERED CSG TOOL TOP. SCREW CSG JT INTO EXISTING STRING. TOOL NOW @ 2711'.
SET PKR @ 3900' & ATTEMPTD TO ESTAB CIRC, COULD NOT. POH W/PKR. SET CKR @ 3925'. SQZD
W/150 SX CLS C CMT. RAN TEMP SURVEY 3925' - 2756'. EST TOC @ 3900'. PERF'D 5-1/2 IN.
CSG @ 3500'. SET CICK @ 3450'. SQZD W/175 SX CLS C CMT. (HAD GOOD RETURNS THROUGHOUT JOB.)
DMPD 1 BBL CMT ON TOP OF CICK. TAGGED TOL @ 2711' & TOC @ 3442'. RAN GR/CBL/CCL FROM
3442' TO 2500'. PT 8-5/8 IN. CSG TO 500# FOR 30 MIN, HELD OK. DO CICK & CMT TO 3980'
& FELL THRU. CO TO 5400'. PERF'D SAN ANDRES 4011' - 4887' (1 JSPF). ACD SAN ANDRES
PERFS 4011' - 4887' W/20,580 GALS 15% HCL. INST PROD EQUIP & RETD WELL TO PROD.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE: J. H. SMITHERMAN TITLE: REGULATORY SUPV. DATE: 12/04/90
TYPE OR PRINT NAME: J. H. SMITHERMAN TELEPHONE NO.: (713) 870-3797

(This space for State Use)

APPROVED BY: _____ TITLE: _____ DATE: _____
CONDITIONS OF APPROVAL, IF ANY:

3A Allen E