

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.E.	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-7

5a. Indicate Type of Lease
State ☐ Fee ☒
5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. CIL WELL ☒ GAS WELL ☐ OTHER ☐	7. Unit Agreement Name
2. Name of Operator SHELL WESTERN E&P INC.	8. Form or Lease Name ARGO "A"
3. Address of Operator P. O. BOX 991, HOUSTON, TEXAS 77001	9. Well No. 7
4. Location of Well UNIT LETTER <u>E</u> <u>1880</u> FEET FROM THE <u>NORTH</u> LINE AND <u>760</u> FEET FROM THE <u>WEST</u> LINE, SECTION <u>22</u> TOWNSHIP <u>21-S</u> RANGE <u>37-E</u> N.M.P.M.	10. Field and Pool, or Wildcat DRINKARD
11. Elevation (Show whether DF, RT, GR, etc.) 3432' DF	12. County LEA

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data.
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☐	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPER. ☐	PLUG AND ABANDONMENT ☐
PULL OR ALTER CASING ☐	OTHER <u>SQUEEZE DRINKARD, RECOMPLETE TO WANTZ ABO, ACID FRAC</u> ☒	CASING TEST AND CEMENT JOB ☐	OTHER ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- Clean out to PBTD @ 6673'.
- Test squeezed Blinbry perf's (5514' - 5951') to 500 psi.
- Set cmt retainer @ #6350'.
- Squeeze Drinkard (6413' - 6659') w/200 sx Class "C" cmt + .3% Halad-9 followed by 200 sx Class "C" cmt + 2% CaCl₂. WDC 24 hrs.
- Drill out cmt retainer @ 6350' and cmt. Pressure test squeeze to 2000 psi.
- Drill out CIBP @ 6700' and clean out to a new PBTD (CIBP @ 7600').
- Perforate Wantz Abo from 7155' to 7217'.
- Run base GR/Temp Survey.
- Acid frac Wantz Abo 6748' - 7223' w/33,000 gals 20% Titan XL acid/5 w/30% CO₂ + 38 ball sealers.
- Install production equipment and return well to production.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

A. J. FORE TITLE SUPERVISOR REG. & PERMITTING DATE APRIL 19, 1985
ORIGINAL SIGNED BY JERRY SEXTON
APPROVED BY DISTRICT 1 SUPERVISOR TITLE _____ DATE APR 22 1985