

Submit 3 Copies  
to Appropriate  
District Office

State of New Mexico  
Energy, Minerals and Natural Resources Department

Form C-103  
Revised 1-1-89

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION  
P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

WELL API NO.

30-025-06742

5. Indicate Type of Lease

STATE ☐

FEE ☒

6. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A  
DIFFERENT RESERVOIR. USE 'APPLICATION FOR PERMIT'  
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:

OIL  
WELL ☐

GAS

WELL ☒

OTHER & WATER SOURCE

2. Name of Operator

Shell Western E&P Inc.

3. Address of Operator

P.O. Box 576 Houston, TX 77001-0576

(WCK 4435)

4. Well Location

Unit Letter C : 660 Feet From The NORTH Line and 1650 Feet From The WEST Line

Section 22

Township 21S

Range 37E

NMPM

LEA

County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

3437' DF

11.

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐

PLUG AND ABANDON ☒

TEMPORARILY ABANDON ☐

CHANGE PLANS ☐

PULL OR ALTER CASING ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐

ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐

PLUG AND ABANDONMENT ☐

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

NOTE: PLUGGING OPERATIONS WILL COMMENCE APPROX 24 HRS FOLLOWING APPROVAL.

1. NOTIFY NMOCD AT LEAST 24 HRS PRIOR TO COMMENCING ANY PLUGGING OPERATIONS.
2. TOH W/4.5 IN. PROD TBG & ESP EQMT.
3. CO TO TOL @ 2682' W/SCRPR.
4. CO LNR TO PBTD @ +/-5365'.
5. SET PKR @ +/-3950' & ESTAB INJ RT INTO SA PERFS 4013' - 4900'. POH W/PKR.
6. SET CICK @ +/-3950'.
7. SQZ SA PERFS W/75 SX CLS C CMT + 0.3% HALAD-9 FOLLOWED BY 75 SX CLS C CMT + 2% CACL2. CAP CICK W/35' CMT.
8. SPOT 22 BBLS MUD (10#/GAL BRINE W/25# GEL/BBL) FROM 3915' TO 3000'.
9. PLACE CMT PLUG FROM 3000' TO 2550' (450' PLUG, 70 SX CMT).
10. SPOT 134 BBLS MUD (10#/GAL BRINE W/25# GEL/BBL) FROM 2550' TO 350'.
11. PLACE CMT PLUG FROM 350' TO SURF' (350' PLUG, 90 SX CMT).
12. CUT OFF CSG 3' BELOW GL.
13. FILL CELL & CLN LOC. INST P&A MARKER & RESTORE LOC AS PER NMOCD RULE 202.
14. CONTACT NMOCD & ARRANGE FOR AN INSPECTION OF THE WELL & LOC.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE W.F.N. Kelldorf TITLE DIV. ENVIRONMENTAL ENGR. DATE 11/05/91

TYPE OR PRINT NAME W. F. N. KELLDORF

TELEPHONE NO. 713/870-3426

(This space for State Use)

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_

CONDITIONS OF APPROVAL, IF ANY:

JAN 07 '92