

NUMBER OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
TRANSPORTER	OIL
	GAS
PRORATION OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION
Santa Fe, New Mexico

MISCELLANEOUS NOTICES

strict Office, Oil Conservation Commission, before the work specified is to begin. A copy will be returned to the school on which will be given the approval, with any modifications considered advisable, or the rejection by the Commission or agent, of the plan submitted. The plan as approved should be followed, and work should not begin until approval is obtained. See additional instructions in the Rules and Regulations of the Commission.

Indicate Nature of Notice by Checking Below

NOTICE OF INTENTION TO CHANGE PLANS		NOTICE OF INTENTION TO TEMPORARILY ABANDON WELL		NOTICE OF INTENTION TO DRILL DEEPER	
NOTICE OF INTENTION TO PLUG WELL		NOTICE OF INTENTION TO PLUG BACK	X	NOTICE OF INTENTION TO SET LINER	
NOTICE OF INTENTION TO SQUEEZE		NOTICE OF INTENTION TO ACIDIZE	X	NOTICE OF INTENTION TO SHOOT (Nitro)	
NOTICE OF INTENTION TO GUN PERFORATE	X	NOTICE OF INTENTION (OTHER) SAND FRAC	X	NOTICE OF INTENTION (OTHER)	

OIL CONSERVATION COMMISSION
SANTA FE, NEW MEXICO

Roswell, New Mexico
(Place)

January 28, 1963
(Date)

Gentlemen:

Following is a Notice of Intention to do certain work as described below at the.....

Shell Oil Company **Argo A** Well No. **10** in **C**
(Company or Operator) (Unit)

NE $\frac{1}{4}$ **NW** $\frac{1}{4}$ of Sec. **22**, T. **21S**, R. **37E**, NMPM., **Hare** Pool
(40-acre Subdivision)

Lea County.

FULL DETAILS OF PROPOSED PLAN OF WORK

(FOLLOW INSTRUCTIONS IN THE RULES AND REGULATIONS)

PROPOSED OPERATION: Abandon Hare, recompleat in Blinbry (Oil).

1. Pull 2" tubing.
2. Set CIBP at 7400' and cap w/cement.
3. Ran GR/N log from 7400' to 2500'.
4. Perforate selective intervals from GR/N from 5700' - 5880' with 3/8" jet shots.
5. Treat w/3000 gallons acid.
6. Swab test.
7. Ran 3" tubing w/FERC and treat w/20,000 gallons lease oil containing 1# sand and 1/20# Mark II Adomite/gallon.
8. Bleed off pressure, pull 3" tubing, check for sand fill and clean out.
9. Run production tubing, swab test, and place on production.

Approved....., 19.....
Except as follows:

Approved
OIL CONSERVATION COMMISSION

By.....

Title.....

Shell Oil Company

Company or Operator

By..... **R. A. Lowery** Original Signed By
R. A. LOWERY

Position..... **District Exploitation Engineer**

Send Communications regarding well to:

Shell Oil Company

Name.....

Address..... **P. O. Box 1858, Roswell, New Mexico**