

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-025-06748
5. Indicate Type of Lease STATE ☐ FEE ☒
6. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL ☒ GAS WELL ☐ OTHER	7. Lease Name or Unit Agreement Name NORTHEAST DRINKARD UNIT
2. Name of Operator SHELL WESTERN E&P INC.	8. Well No. 903
3. Address of Operator P. O. BOX 576, HOUSTON, TX 77001 (WCK 4435)	9. Pool name or Wildcat NORTH EUNICE BLINEBRY-TUBB- DRINKARD OIL & GAS
4. Well Location Unit Letter <u>M</u> : <u>660</u> Feet From The <u>SOUTH</u> Line and <u>660</u> Feet From The <u>WEST</u> Line Section <u>22</u> Township <u>21S</u> Range <u>37E</u> NMPM <u>LEA</u> County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3432' DF	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK ☐	REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐	ALTERING CASING ☐
PULL OR ALTER CASING ☐	COMMENCE DRILLING OPNS. ☐
OTHER: ☐	PLUG AND ABANDONMENT ☐
	CASING TEST AND CEMENT JOB ☐
	OTHER: <u>Cmt sqzd, CO, OAP & Acc</u> ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

10-23 to 11-09-89:

POH w/prod equip. CO to 6428' (tagged fill). Set CIBP @ 5670' & pkr @ 4350'. Pres tstd sqzd SA perfs 3990' - 4027' & sqz holes 4100' - 4300' to 500# for 15 min, held OK. Rel pkr & reset @ 5660'. Pres tstd CIBP to 500# for 15 min. Rel pkr & reset @ 5350'. Etab inj rt. Sqzd Blinebry perfs 5474' - 5648' w/150 sx Cls "C" cmt + .3% CF-1 + 100 sx Cls "C" cmt + 2% CaCl₂. Rel pkr & POH. Tagged TOC @ 5291'. DO cmt to 5660'. Pres tstd sqz to 500# for 15 min, held OK. KO CIBP & pushed to 5704'. DO CIBP remnants & cmt to 5942', fell out of cmt. Tagged fill @ 6454'. CO to 6460' & tagged CIBP. Drld on plug & plug fell to 6495'. Drld on plug & fell to 6499'. Drld up CIBP remnants & CO fill/fm to 6623'. Couldn't make further hole due to fm sloughing off. Circ'd cln. Re-tagged fill @ 6623'. Perfd Blinebry/Tubb/Drinkard 5720' - 6498' (1 JSPF & 2 JSPF). Acc perfs 5720' - 6498' & Drinkard OH 6521' - 6623' w/7980 gals 15% HCl + 1500# rock salt. Inst prod equip & ret'd to prod.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE J. H. Smitherman TITLE REGULATORY SUPV. DATE 1-08-90
TYPE OR PRINT NAME J. H. SMITHERMAN (713) 870-3797 TELEPHONE NO.

(This space for State Use)

ORIGINAL SIGNED BY JERRY SEXTON

APPROVED BY DISTRICT I SUPERVISOR TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY:

JAN 12 1990