STATE OF NEW MEXICO ENERGY AND MINERALS DEPARTMENT

/(G1)//(G1)		
COPICS ACCEIVED	<u> </u>	
DISTRIBUTION		
SANTA FE		
FILE		
U.3.G.3.		
LAND OFFICE		
OPPHATOR	l l	1

OIL CONSERVATION DIVISION P. O. BOX 2088

Form C-101 . Revised 10-1-78

DISTRIBU	10H	K641264 12-1-10
SANTA FE	SANTA FE, NEW MEXICO 87501	
FILE		5a. Indicate Type of Leuse
U.3.G.3.		State Foo X
LAND OFFICE		5. State Oil & Gas Lease No.
OPERATOR		
	SUNDRY NOTICES AND REPORTS ON WELLS	
(DO NOT USE	THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.	
	USE "APPLICATION FOR PERMIT	7. Unit Agreement Name
۱.	CAS	
WELL X	WELL OTHER-	8. Farm or Lease Name
2. Name of Operator	·	TURNER
	CONDANY	9. Well No.
SHELL OIL		9. Well rio.
3. Address of Opera		6
P. O. BOX	991, HOUSTON, TX 77001	10. Field and Pool, or Wildcat
4. Location of Well	•	BLINEBRY OIL AND GAS
	M	DETINEDRI OTE AND OUS
UNIT LETTER	[1] ,	
	T 22 21-S 37-E NUMBER.	
WES	T LINE, SECTION 22 TOWNSHIP 27-S RANGE 37-E NAPH.	
,		12. County
mm	15. Elevation (Show whether DF, RT, GR, etc.)	
	\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\	LEA ()
inninn.		her Data
ló.	Check Appropriate Box To Indicate Nature of Notice, Report or Other	T REPORT OF:
	NOTICE OF INTENTION TO:	I REFORT OF
••		
	PLUG AND ABANDON REMEDIAL WORK	ALTERING CASING
PERFORM REMEDIAL	COMMENCE DRILLING OPHS.	PLUG AND ABANDONMENT
TEMPORARILY ABAN	104 II	
PULL OR ALTER CAS	CHANGE PLANS CASING TEST AND CEMENT JOB	CC. DE ENTED RITHERRY X
PULL OR ALIEN CAS	OTHER SQUEEZE SAN ANDR	ES: RE-ENTER BLINEBRY X
	. □ \ AND ACIDIZED	(WELL TA'D 6-07-72)
OTHER		
	sed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including	g estimated date of starting any proposed
17. Describe Propo work) SEE RU	LE 1 103.	
work) see	Con Andres nonfe 30	000' to 4027' (10 holes)
4-02-83:	Set cement retainer @ 3850' and squeezed San Andres perfs 39	790 : 00 4027 (10 1101037
. 02 001	w/150 sx Class "C" cmt. WUC 24 hrs.	
4 04 02.	Drilled out cmt retainer @ 3850' and cement to 3910'.	
4-04-83:		
	Drilled cmt to 4030' and tested squeeze holes to 500# - held	ink Drilled out cement
4-05-83:	Drilled cmt to 4030' and tested squeeze notes to 500# - here	OK. Billied out come
4-06-83:	Drilled out cmt to 4120' and fell free. Pressure tested to	500# - held UK.
4-00-03.	Diffred out care to file	
4-07-83:	Drilled out CIBP @ 5650'.	
		HO3 NEA
4-08-83:	Acid treated Blinebry perfs 5714' to 5932' w/6,000 gals 15%	HCI-NEA.
4-00-03.	Meta created billion 3 Parts	•
	turtion agricument and noturned well to product	ion.
4-09-83:	Installed production equipment and returned well to product	
	·	•
	•	
	•	
•		•
	2 to 142 of	
18. I hereby certi	y that the information above is true and complete to the best of my knowledge and belief.	
	· ()	
<i>-</i> \$/.	LUSTICE A. J. FORE TITLE SUPERVISOR REG. & PERMITTI	NG JUNE 9, 1983
Suren alle	e cultistics. A. J. FORE TITLE SUPERVISOR REG. & PERMILLI	4444
J	ORIGINAL SIGNED BY JERRY SEXTON	OATE JUN 15
	DISTRICT I SUPERVISOR	DAYE UUIY LA
	Minimum 1 - A - Little	

