# NEW MEXICO OIL CONSERVATION COMMISSION CE OCC

Santa Fe, New Mexico

### MISCELLANEOUS NOTICES23 M 11:45

Submit this notice in TRIPLICATE to the District Office, Oil Conservation Commission, before the work specified is to begin. A copy will be returned to the sender on which will be given the approval, with any modifications considered advisable, or the rejection by the Commission or agent, of the plan submitted. The plan as approved should be followed, and work should not begin until approval is obtained. See additional instructions in the Rules and Regulations of the Commission.

#### Indicate Nature of Notice by Checking Below

Notice of Intention to Change Plans	Notice of Intention to Temporarily Abandon Well		Notice of Intention to Drill. Deeper	
Notice of Intention to Plug Well	Notice of Intention to Plug Back		Notice of Intention to Set Liner	
Notice of Intention to Squeeze	NOTICE OF INTENTION TO ACIDIZE		Notice of Intention to Shoot (Nitro)	
Notice of Intention to Gun Perforate	NOTICE OF LITENERS MPLETE	x	Notice of Intention (Other)	

OIL CONSERVATION COMMISSION SANTA FE, NEW MEXICO

Roswell, New Mexico

August 26, 1960

(Place) (Date)

Gentlemen:

Following is a Notice of Intention to do certain work as described below at the..... Shell Oil Company Turner 7 L (Company or Operator NW SW 37E 21S Brunson R......NMPM., .... .....Poəl (40-acre Subdivision) Lea

### FULL DETAILS OF PROPOSED PLAN OF WORK

## (FOLLOW INSTRUCTIONS IN THE RULES AND REGULATIONS) RECOMPLETE FROM EILENBURGER TO HARE

- Run GR/CCL from 8050' 7600'. 1.
- Set CIEP @ 8030' & cap w/l sx. cement. 2.

.....County.

- Pressure test casing to 1100 psi. 3.
- Perforate Connell Sand w/8-way "frac" jet" at 7974". Ŀ.
- 5. 6. Run tubing & wash perforations w/100 gallons MCA, inject 900 gallons MCA.
- Swab test.
- If necessary, pull tubing, run 3" X-line tubing w/packer and fracture treat w/10,000 gallons lease oil plug 1# 20-40 mesh and per gallon & sufficient FLA to obtain less 7. than 10 cc spurt loss and 30-minute fluid loss less than 20 cc.
- 8. Bleed off pressure, pull 3" tubing, run 2" tubing.
- 9. Swab test and place on production.

AUG 2 ( 19.00) 19		Shell Oil Company
Except as follows:	By	Company or Operator Original Signed By R. A. Lowery R. A. LOWERY
Approved	Position	District Exploitation Engineer Send Communications regarding well to:
OIL CONSERVATION COMMISSION	Name	Shell Oil Company
Title	Address	Box 845, Roswell, New Mexico