

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.O.S.	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-7

5a. Indicate Type of Lease
State ☐ Fee ☒

5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐	7. Unit Agreement Name NORTHEAST DRINKARD UNIT
2. Name of Operator SHELL WESTERN E&P INC.	8. Farm or Lease Name NORTHEAST DRINKARD UNIT
3. Address of Operator P. O. BOX 576, HOUSTON, TX 77001 (WCK 4435)	9. Well No. 904
4. Location of Well UNIT LETTER <u>K</u> <u>2065</u> FEET FROM THE <u>SOUTH</u> LINE AND <u>1700</u> FEET FROM THE <u>WEST</u> LINE, SECTION <u>22</u> TOWNSHIP <u>21S</u> RANGE <u>37E</u> N.M.P.M.	10. Field and East, or West, or North, or South, or Blinebry-Tubb-Drinkard Oil & Gas
11. Elevation (Show whether DF, RT, GR, etc.) 3423' DF	12. County LEA

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data.
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☐	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPERATIONS ☐	PLUG AND ABANDONMENT ☐
PULL OR ALTER CASING ☐	OTHER ☐	CASING TEST AND CEMENT JOB ☐	OTHER ☒ Sqzd, OAP & Acid

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1703.

5-02 to 5-10-88:

POH w/prod equip. Set CIBP @ 6470'. Set pkr @ 6236'. Sqzd Drinkard perfs 6390' - 6462' w/25 sx Cls "C" cmt + .3% Halad-9 followed by 100 sx Cls "C" cmt + 2% CaCl₂. POH w/pkr. DO cmt 6250' - 6465'. Pres tstd sqz to 500#, held OK. DO CIBP @ 6470' & cmt to 6626'. Perf'd Blinebry 5713' - 5941'. Acid Drinkard OH 6480' - 6626' w/5250 gals 15% HCl-NEA + 1000# rock salt. Set RBP @ 6310'. Acid Blinebry perfs 5713' - 5941' w/10,500 gals 15% HCl-NEA + 1000# rock salt. POH w/RBP. CO from 6610' to 6626'. Installed prod equip & ret'd well to prod.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED A. J. FORE TITLE SUPERVISOR REG. & PERMITTING DATE 8-18-88

ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT I SUPERVISOR

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY: