

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

## SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input checked="" type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER		7. Unit Agreement Name
2. Name of Operator Shell Oil Company		8. Farm or Lease Name Turner
3. Address of Operator P. O. Box 1509, Midland, Texas 79701		9. Well No. 14
4. Location of Well UNIT LETTER <u>J</u> <u>2310</u> FEET FROM THE <u>south</u> LINE AND <u>2310</u> FEET FROM THE <u>east</u> LINE, SECTION <u>22</u> TOWNSHIP <u>21S</u> RANGE <u>37E</u> N.M.P.M.		10. Field and Pool, or Wildcat Hare Simpson
11. Elevation (Show whether DF, RT, GR, etc.) 3423 DF		12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
-------------------------	-----------------------

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	
		OTHER <u>Complete in Hare Simpson</u> <input checked="" type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1-15-75 to 2-4-75

1. Set CIBP at 7550' and capped with 35' cement.
2. Perforated 5 1/2" casing w/4 JSPF @ 7412-15, 7418-26, 7436-38', 7448-54', 7475-85', 7506-16 (156 holes).
3. Acidized perforations 7412-7516 w/6000 gal 7 1/2% HCl.
4. Shut well in pending further operations.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED N. W. Harrison for N. W. Harrison TITLE Staff Production Engineer DATE 3-10-75

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_

CONDITIONS OF APPROVAL IF ANY: