

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

5a. Indicate Type of Lease	
State ☒	Fee ☐
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. ☐ OIL WELL ☐ GAS WELL ☐ OTHER WATER SOURCE	7. Unit Agreement Name
2. Name of Operator SHELL WESTERN E&P INC.	8. Farm or Lease Name TURNER
3. Address of Operator P. O. BOX 576, HOUSTON, TEXAS 77001 (WCK 4435)	9. Well No. 16
4. Location of Well UNIT LETTER M 330 FEET FROM THE SOUTH LINE AND 660 FEET FROM THE WEST LINE, SECTION 22 TOWNSHIP 21-S RANGE 37-E N.M.P.M.	10. Field and Pool, or Wildcat HARE-SAN ANDRES GAS
11. Elevation (Show whether DF, RT, GR, etc.) 3427' DF	12. County LEA

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data.
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐
PULL OR ALTER CASING ☐
OTHER ☐

PLUG AND ABANDON ☐
CHANGE PLANS ☐
OTHER ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐
COMMENCE DRILLING OPER. ☐
CASING TEST AND CEMENT JOBS ☐
OTHER Sqzd Penrose Skelly Grayburg & recompleted to San Andres for wtr source; tst pmp ☒
ALTERING CASING ☐
PLUG AND ABANDONMENT ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1703.

6-03 to 6-21-88:

POH w/prod equip. Set pkr @ 3350'. Sqzd Penrose Skelly Grayburg perfs 3684' - 3778' w/75' sx Cls "C" cmt + .3% Halad-9 followed by 125' sx Cls "C" cmt + 2% CaCl₂. POH w/pkr. DO cmt 3380' - 3778'. Pres tstd sqz to 500#, held OK. DO CIBP @ 3925'. DO plug @ 3999' & frac sd & cmt to 4065'. Drld on junk & cmt ret. Lost 2 cones off bit. Mld over cones & cmt ret. Rec cones & cmt ret. Drld cmt to 4190'. DO CIBP @ 4190'. DO scale to 4810' & fell thru to 5056'. Perf'd San Andres 4073' - 4960' (1 JSPP). Set RBP @ 4990'. Spotted 1000 gals 15% HCl-NEA from 4960' to 3960'. Acid perfs 4004' - 4960' w/24,780 gals 15% HCl + 5000# rock salt. POH w/RBP. Installed prod equip & tandem BHP bombs. Returned well to prod.

6-25-88:
SI well.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED A. J. FORE TITLE SUPERVISOR REG. & PERMITTING DATE 6-28-88

ORIGINAL SIGNED BY JERRY SEXTON

APPROVED BY DISTRICT 1 SUPERVISOR TITLE 7 A Penrose Skelly G. DATE

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED

JUL 1 1988

ODJ
HOBBS OFFICE