ARCO Oil and Ga. Dmpany Permian District Post Office Box 1610 Midland, Texas 79702 Telephone 915 684 0100



February 4, 1986

Oil Conservation Commission P. O. Box 1980 Hobbs, New Mexico 88240

Re: S. J. Sarkeys #3 Wantz Abo Pool Unit I, 23, 218, 37-E

Mr. Jerry Sexton:

Concerning your letter dated 12-18-85, Jack Lowder, Engineer over subject well, had telephone conversation with you on January 16, 1986, and got verbal permission to proceed as shown on attached C-103.

The reasoning for the request was:

- 1. ARCO currently has down-hole commingling permit for the Drinkard and Blinebry.
- 2. Obtaining reservoir pressures and production rates would be a necessity in obtaining a triple down-hole commingling permit and would greatly speedup the application process.
- 3. The Wantz Abo could be easily isolated while testing the other two (2) zones.
- 4. The Wantz Abo is to be isolated with RBP and the down-hole commingled Drinkard and Blinebry is to be rod pumped during the application process for triple down-hole commingling.

The Wantz Abo was produced under a packer thru January 13, 1986. On January 14, a RBP and packer was used to obtain reservoir pressure and production rate for the Drinkard.

We are currently in the third step and last zone (Blinebry) to be tested. A 72 hour pressure buildup was started 2-1-86. After the buildup, the Blinebry is to be stimulated and swab tested for a production rate. Lastly, the Wantz-Abo will be isolated with a RBP and the down-hole commingled Drinkard and Blinebry will be rod pumped until such time a triple down-hole commingling permit is obtained.

If you have any questions, please call 915-684-0312.

Ken Welosnell Ken W. Gosnell

Engr. Techen Spates Company is a Division of AtlanticRichtle-dCompany

ENERGY MO MINERALS DEPARTMENT		·	V
DISTRIBUTION		ATION DIVISI	P
BANTA FE			Form C-183 Revised 18-1-78
FILE	JANTA FE, N	EW'MEXICO \$7501	
U.S.O.S.			Se. Indicate Type of Losse State 7 For X
DERATOR			3. Stote Oil & Gas Loase No.
SUNDRY NOTICES AND REPORTS ON WELLS WE THIS FOR FOR PROPAGATE TO BALL OR TO BEFER OF PLUE BALE TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PENNIT -" (FORM C-101) FOR SUCH PROPAGALD.)			
	ofuga-		7. Unit Agreement Name
2. Neme of Operator ARCO 011 and Gas Company			8. Fam or Lease Hene
Division of Atlantic Richfield Company			S. J. Sarkeys
3. Address of Operator			9. Vell No.
P. O. Box 1710, Hobbs, New Mexico 88240			3
4. Location of Well			10. Field and Pool, or Wildcat
UNIT LETTER 2310 FEET FROM THE South LINE AND JEET FROM			Blinebry/Drinkard
THE <u>Bast</u> LINE, SECTION	TOWNSHIP	215 RANGE 37E	
	15. Elevation (Show when	ther DF. RT. GR. etc.)	12. County
	3405' G	-	Lea
16. Check At	opropriate Box To Indicat	e Nature of Notice Report of	Other Date
Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:			
			ENT REFORT OF.
PERFORM BEMEDIAL WORK	PLUE AND ABANDON	REMEDIAL WORK	
TEMP68A4 LT ABANDON			PLUS AND ADANDONMENT
PULL OR ALTER CASTNE	CHANGE PLANS	CASING TEST AND CEMENT JOB	_
Do optom Vorte A	ha nana	0THER	
ernen Re-enter Wantz Abo zone, Perforate X & Acidize Wantz Abo, Drkd & Blinebry			
17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give persinent dates, including estimated date of starting any proposed			
whe set RULE 1103.			
 RU, POH w/rods & pump. NU BOP. POH w/tbg. RIH w/4-3/4" bit, DO cmt retr @ 6650', cmt & CIBP @ 6800'. CO to orig PBD7320'. POH. 			
Run GR-CNL from PBD to TOC @ 5330'.			
3. Perf Wantz Abo (approx 40 holes), Drinkard (approx 10 holes) & Blinebry (approx 5 holes) w/l JSPF using 3-1/8" gun. RIH w/FBRC pkr, set @ 6710'. Acidize Wantz Abo perfs w/3500			
gals 15% NEFE HCL, flush to btm perf w/2% KCL. Swab test. Run Base GR-TS.			
4. Acid frac Wantz Abo w/17,500 gals 15% NEFE gelled acid tagged w/liquid RA mat'l & 17,500			
gal CO ₂ (50% CO ₂). Procedure to be determined after log evaluation. Flush to btm perf			
w/2% KCL w/50% CO2. Run GR-TS. Flow/swab test.			
5. POH w/pkr. RIH w/RBP & pkr, set RBP @ 6680', pkr @ 6200'. Acidize Drinkard perfs w/3500			
gals 15% NEFE HCL, flush to btm perf w/2% KCL. Swab test.			
 Rel pkr & RBP. Reset RBP @ 5925', pkr @ 5550'. Acidize Blinebry perfs w/3000 gals 15% NEFE HCL, flush to btm perf w/2% KCL. Swab test. 			
7. Rel pkr & RBP. POH.	RIH W/CA. ND ROP	Run pump & rods. Return	to production
	りちて	BUW SIN	MIDLAND CF - MIDLAND
	MBC		G - MILLING AND
	ANDV	7 1985	THES - MIDLA
	NUY		DEES - MIDLAND
18. I hereby certify that the information at	bove is true and complete forthe	Abi Fitnergedes and belief.	wind and a state of the state o
D.D. Metdas	nil me	Dist Drlg. Supv.	BATE 10/25/85
ORIGINAL SIGNED BY J DISTRICT I SUPE			OCT 2 9 1985
			BATE
CONDITIONS OF APPROVAL, IF ANY:		APPROVED PERM	4 7

ł

.

;

.