NEW N KICO OIL CONSERVATION COMMISTON Santa Fe, New Mexico

(Form C-104)
Revised 7/1/57

REQUEST FOR (OIL) - (ALLOWABLE)

New Well Recompletion

This form shall be submitted by the operator before an initial allowable will be assigned to any completed Oil or Gas well. Form C-104 is to be submitted in QUADRUPLICATE to the same District Office to which form C-108 was sent. The allowable will be assigned effective 7:00 A.M. on date of completion or recompletion provided this form is filed during calendar month of completion or recompletion. The completion date shall be that date in the case of an oil well when new oil is delivered into the stock tanks. Gas must be reported on 15.025 psia at 60° Fahrenheit.

Hebbs. New Mexico.

June 19. 1962

(C	Compan	y or Oper	Company rator) 23	, _T 21s	, R	37 <u>s</u>	., NMPI	И.,	<u>.</u>	7 Bl	nebry		Pc
Unit Letter Los. Please indicate location:			County I	Data Smid	ided 8	/22/52		Date	Drillin	Complet	æd		
Ple	ease in	dicate lo	cation:	Top Oil/Ga	ıs Pay	5630		_ _Name of	Prod.	Form.	Bline	bry	
)	С	В	•	PRODUCING Perforation	INTERVAL -	-							
6	F	G.	Н	Perforation	ons	-		Depth Casing	Shoe	•	De Tu	epth ubing	5802
;	K	J	I		rod. Test:								Chol
1	N	0	P										Choke min. Size
oing ,C	Casing	and Geme	nting Reco	GAS WELL 1 Natural Promote Method of Test After	rod. Test: Testing (pitot, ba	ck pressu Treatment	etc.):		MCF/Day;	Chcke	Sizeflowed
Size 10 3/	/4	323	250)	Method of Test Afte Choke Siz	rod. Test: Testing (r Acid or e	pitot, ba Fracture Method o	ck pressu Treatment f Testing	nre, etc.):	ls used,	MCF/Day;	Choke Hours	Sizeflowedwater, oil, as
•	/4 /8	Feet	Sax	Method of Test Afte Choke Size Acid or Fresand): 20 Casing Press. Oil Trans	rod. Test: Testing (r Acid or e racture Tr ,000 ga 30 Tu porter	pitot, ba Fracture Method o eatment (0 ls lse. bbing ess.	ck pressured for Testing Give amount crude O oil	nts of m + 40 first r run to t):	ls used, # sand 6/17	MCF/Day; such as + 1/2 /62	Choke Hours	Sizeflowed
Sire 10 3/ 7 5/ (line 5 1/ marks:	/4 /8 er) /2 GC	323 3180 7055 R 10,4	250) 1253 425 27; Gty	Method of Test Afte Choke Siz Acid or Fi sand): 20 Casing Press.	rod. Test: Testing (r Acid or e reacture Tr ,000 ga 30 Pr porter T porter S porter S porter S	pitot, ba Fracture Method o eatment (0 18 180 bbing ess. Relly //13 -	ck pressure freatment for Testing Give amount crude O Date O oil ON Mexicon ON Company And	nts of m + 40 first r run to t Lee Pi	nateria OOO new canks pe Li	sand 6/17 ine Ce	MCF/Day; such as + 1/2 /62	Chcke Hours acid, O# Ad	Sizeflowedwater, oil, as