

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

5a. Indicate Type of Lease
State ☐ Fee ☒
5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐	7. Unit Agreement Name NORTHEAST DRINKARD UNIT
2. Name of Operator SHELL WESTERN E&P INC.	8. Farm or Lease Name NORTHEAST DRINKARD UNIT
3. Address of Operator P. O. BOX 576, HOUSTON, TX 77001 (WCK 4435)	9. Well No. 810
4. Location of Well UNIT LETTER <u>D</u> <u>660</u> FEET FROM THE <u>NORTH</u> LINE AND <u>660</u> FEET FROM THE <u>WEST</u> LINE, SECTION <u>23</u> TOWNSHIP <u>21S</u> RANGE <u>37E</u> NMPM.	10. Field and Pool, or Wildcat NORTH EUNICE BLINEBRY- TUBB-DRINKARD OIL & GAS
11. Elevation (Show whether DF, RT, GR, etc.) 3402' GR	12. County LEA

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data.
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐
PULL OR ALTER CASING ☐
OTHER ☐

PLUG AND ABANDON ☐
CHANGE PLANS ☐
OTHER ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐
COMMENCE DRILLING OPER. ☐
CASING TEST AND CEMENT JOB ☐
OTHER OAP & Acid ☒
ALTERING CASING ☐
PLUG AND ABANDONMENT ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1703.

8-08 to 8-10-88:

POH w/prod equip. Perf'd Tubb 6008'-46' (1 JSPF & 1 JSP2F). Set RBP @ 6155'. Acid perfs 6008'-46 w/2100 gals 15% HCl-NEA. Installed prod equip & ret'd well to prod.

8-26 to 9-01-88:

POH w/prod equip & RBP @ 6155'. DO cmt 6545'-56'. DO CIBP @ 6556' & CO to 6617'. Perf'd Blinebry 5650' - 5933' (1 JSPF & 1 JSP2F); Tubb 5960'-73' (1 JSPF); Drinkard 6511'-45' (1 JSPF). Ran GR/Temp log 6200' - 5500'. Acid OH 6573' - 6617' w/3150 gals 15% HCl-NEA + 500# rock salt, set RBP @ 6560'. Acid perfs 6409' - 6545' w/3150 gals 15% HCl-NEA. Reset RBP @ 5994'. Acid perfs 5650' - 5973' w/7350 gals 15% HCl-NEA + 1000# rock salt. POH w/RBP. Installed prod equip & ret'd well to prod.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED A. J. FORE

TITLE SUPERVISOR REG. & PERMITTING

DATE 9-12-88

Orig. Signed by
Paul Kautz
Geologist

APPROVED BY _____

TITLE _____

DATE SEP 13 1988

CONDITIONS OF APPROVAL, IF ANY: