

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

5a. Indicate Type of Lease	
State ☐	Fee ☒
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. CIL WELL ☒ CAS WELL ☐ OTHER ☐	7. Unit Agreement Name NORTHEAST DRINKARD UNIT
2. Name of Operator SHELL WESTERN E&P INC.	8. Farm or Lease Name NORTHEAST DRINKARD UNIT
3. Address of Operator P. O. BOX 576, HOUSTON, TX 77001 (WCK 4435)	9. Well No. 810
4. Location of Well UNIT LETTER <u>D</u> <u>660</u> FEET FROM THE <u>NORTH</u> LINE AND <u>660</u> FEET FROM THE <u>WEST</u> LINE, SECTION <u>23</u> TOWNSHIP <u>21S</u> RANGE <u>37E</u> N.M.P.M.	10. Field and Pool, or Wildcat NORTH EUNICE BLINEBRY-TUBB-DRINKARD OIL & GAS
11. Elevation (Show whether DF, RT, GR, etc.) 3402' GR	12. County LEA

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data.
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐
PULL OR ALTER CASING ☐	OTHER <u>OAP (cmt sqz if necessary) & Acdz</u> ☒

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐	ALTERING CASING ☐
COMMENCE DRILLING OPERATIONS ☐	PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐	OTHER ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1703.

1. POH w/prod equip.
2. Perf Tubb 6008'-46' (1 JSPP).
3. Set RBP @ 6300'.
4. Acdz perfs 6008'-46' w/2100 gals 15% HCl-NEA.
5. POH w/RBP.
6. Install prod equip & ret well to prod (tstg Blinebry/Tubb/Drinkard).
7. POH w/prod equip.
8. Cmt sqz Tubb perfs if zone tstg shows the Tubb to be a gas interval.
9. DO CIBP @ 6556' (cmt cap @ 6544'). CO to 6610'.
10. Perf Blinebry 5650'-5944' (1 JSPP); Tubb 5960'-73' (1 JSPP); Drinkard 6511'-45' (1 JSPP).
11. Run GR/Temp log from 6200' - 5500'.
12. Acdz perfs 5650' - 6545' & OH 6573' - 6610' w/13,650 gals 15% HCl-NEA + 1500# rock salt.

(CONTINUED ON REVERSE SIDE)

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED A. J. FORE TITLE SUPERVISOR REG. & PERMITTING DATE 7-27-88

APPROVED BY _____ TITLE _____ DATE AUG 01 88

CONDITIONS OF APPROVAL, IF ANY:

13. Run GR/Temp Log from 6200' - 5500'.
14. Install prod equip & ret well to prod.