

NUMBER OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.S.	
LAND OFFICE	
TRANSPORTER	OIL
	GAS
PERFORATION OFFICE	
OPERATOR	

**NEW MEXICO OIL CONSERVATION COMMISSION**  
**Santa Fe, New Mexico**

**4-OCC**  
**1-Kirby Pet. Co.**  
**1-File**

## MISCELLANEOUS NOTICES

strict Office, Oil Conservation Commission, before the work specified is to begin. A copy will be required to the sender on which will be given the approval, with any modifications considered advisable, or the rejection by the Commission or agent, of the plan submitted. The plan as approved should be followed, and work should not begin until approval is obtained. See additional instructions in the Rules and Regulations of the Commission.

**Indicate Nature of Notice by Checking Below**

NOTICE OF INTENTION TO CHANGE PLANS		NOTICE OF INTENTION TO TEMPORARILY ABANDON WELL		NOTICE OF INTENTION TO DRILL DEEPER	
NOTICE OF INTENTION TO PLUG WELL		NOTICE OF INTENTION TO PLUG BACK	<b>X</b>	NOTICE OF INTENTION TO SET LINER	
NOTICE OF INTENTION TO SQUEEZE		NOTICE OF INTENTION TO ACIDIZE		NOTICE OF INTENTION TO SHOOT (Nitro)	
NOTICE OF INTENTION TO GUN PERFORATE		NOTICE OF INTENTION (OTHER)		NOTICE OF INTENTION (OTHER)	

OIL CONSERVATION COMMISSION  
 SANTA FE, NEW MEXICO

**Hobbs, New Mexico**  
 (Place)

**November 5, 1964**  
 (Date)

Gentlemen:

Following is a Notice of Intention to do certain work as described below at the.....

**Tidewater Oil Company** **D. A. Williamson** Well No. **3** in.....  
 (Company or Operator) **Lease** (Unit)  
**SW**  $\frac{1}{4}$  **NW**  $\frac{1}{4}$  of Sec. **23**, T. **21 S**, R. **37 E**, NMPM, **Blaine** Pool  
 (40-acre Subdivision)  
**Lea** County.

### FULL DETAILS OF PROPOSED PLAN OF WORK (FOLLOW INSTRUCTIONS IN THE RULES AND REGULATIONS)

**Well #3, formerly Kirby Williamson #1, is presently completed in the Drinkard zone and is producing 5 BOPD from open hole 6456-6600'. It is proposed to plug the Drinkard and complete in the Blaine oil zone as follows:**

**Set cast iron bridge plug at 6430', dump two sacks cement on plug. Run Gamma Ray-Neutron log, pick zone and perforate 5½ casing. Run 3" tubing and treat perforations w/1000 gals. acid, using ball sealers. Fracture w/30,000 gals. lease oil and 30,000# sand. Pull 3", run 2-3/8 tubing and hookwall packer, set packer at approximately 5700'.**

Approved....., 19.....  
 Except as follows:

Approved  
 OIL CONSERVATION COMMISSION

By.....

Title.....

**Tidewater Oil Company**  
 Original Signed By

By..... **C. L. WADE**.....

Position..... **Area Supt.**.....

Send Communications regarding well to:

Name..... **C. L. Wade**.....

Address..... **Box 249, Hobbs, New Mexico**.....