NUMBER OF COPIES RECEIVED								
01	STRIBUTION							
SANTA FI			NEW MEXICO OIL CONSERVATION COMMISSION					
U.S.G.S.			Santa Fe, New Mexico					
TRANSPORTER	OIL		1					
PRORATION OFFICE			MISCELLANEOUS NOTICES					
OPERATOR			MINOCLUSIE					

4-0CC 1-File 1-Kirby Petroleum

MISCELLANEOUS NOTICES

strict Office, Oil Conservation Commission, before the work specified is to begin. A copy will be returned to the sender on which will be given the approval, with any modifications considered advisable, or the rejection by the Commission

or agent, of the plan submitted. The plan as approved should be followed, and work should not begin until approval is obtained. See additional instructions in the Rules and Regulations of the Commission.

Indicate Nature of Notice by Checking Below

Notice of Intention to Change Plans	NOTICE OF INTENTION TO TEMPORARILY ABANDON WELL	NOTICE OF INTENTION TO DRILL DEEPER				
NOTICE OF INTENTION TO PLUG WELL	NOTICE OF INTENTION TO PLUG BACK	X	NOTICE OF INTENTION TO SET LINER			
NOTICE OF INTENTION TO SQUEEZE	NOTICE OF INTENTION TO ACIDIZE		Notice of Intention to Shoct (Nitro)			
Notice of Intention to Gun Perforate	Notice of Intention (Other)		Notice of Intention (Other)			

OIL CONSERVATION COMMISSION SANTA FE, NEW MEXICO

Hobbs, New Mexico (Place)

December 9, 1964 (Date)

Gentlemen:

Tidewater Oil Company Following is a Notice of Intention to do certain work as described below at the.....

	D.	A.	Wij	111	in son			Well	No	4	in	C
(Company or Operator)					Leas							(Unit)
	Т	21	S	, R.	37	E	,NMPM.,	•••••	B	linebry		Pool

LeaCounty.

> FULL DETAILS OF PROPOSED PLAN OF WORK (FOLLOW INSTRUCTIONS IN THE RULES AND REGULATIONS)

Well formerly Kirby Petroleum Company's D. A. Williamson #2 and is completed in the Blinebry gas zone thru casing perforations 5552-5615'. It is proposed to plug off the gas zone and complete as a Blinebry oil well as follows:

Squeese Blinebry gas perforations with cement. Drill out cement and test. Drill out cement and CIBP at 5680'. Set CIBP at 5950', and dump two sacks cement on top of MP. Run GR/N, pick Blinebry oil perforations and perforate at approximately 5750-5850'. Run $3\frac{1}{2}$ " frac tubing and treating packer. Spot acid across perforations, pull up and set packer at 5650'. Treat with 1000 gals. acid using ball sealers, 30,000 gals. lease oil and 30,000# sand. Full frac tubing and run 2-3/8" tubing with LW BOC packer. Set packer at 5700'. Swab well in.

Approved, 19	Tidewater Oil Company
Except as follows:	Company or Operator Original Signed By
Approved OIL CONSERVATION COMMISSION	By
By	Name
Title	Address Box 249, Hobbs, New Mexico

--

i e solo de la companya de

. · · · · · ·

1. 2.

· · ·

t t t t