

Submit 3 Copies  
to Appropriate  
District Office

State of New Mexico  
Energy, Minerals and Natural Resources Department

Form C-103  
Revised 1-1-89

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION  
P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-025-08703
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. SWD - 161
7. Lease Name or Unit Agreement Name TRUCKERS SALT WATER DISPOSAL STATE - G
8. Well No. 6
9. Pool name or Wildcat

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/> SWD <input type="checkbox"/>	
2. Name of Operator UNICHEM INTERNATIONAL INC.	
3. Address of Operator P O BOX 1499, HOBBS, NM 88240	
4. Well Location Unit Letter <u>L</u> : <u>3300</u> Feet From The <u>NORTH</u> Line and <u>660</u> Feet From The <u>WEST</u> Line Section <u>6</u> Township <u>21 S</u> Range <u>36 E</u> NMPM LEA County 10. Elevation (Show whether DF, RKB, RT, GR, etc.) <u>3554' DF</u>	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- Pumped 100 sacks cement at 3,070'. Tagged top of cement at 3,070', test to 500 PSI, spot 30 sacks cement from 3,070' to 2,894'.
- Perforate at 1,268', spot 30 sacks cement outside 7" casing and pump 30 sacks cement inside 7" casing.
- Tag cement at 1,020', perforate at 248', pumped 60 sacks cement outside 7" casing, 40 sacks cement 7" casing to surface.
- Pressure tested to 500 PSI, removed wellhead, set marker.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Richard Brakey TITLE Vice President DATE 1-20-94

TYPE OR PRINT NAME RICHARD BRAKEY TELEPHONE NO. 393-7751

(This space for State Use)

APPROVED BY Gary W. Wink TITLE ORIGINAL SIGNED BY GARY WINK FIELD REP. II DATE JAN 26 1994

CONDITIONS OF APPROVAL, IF ANY

SAD