

Submit 3 Copies To Appropriate District Office
District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
Revised March 25, 1999

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

WELL APENO. 30-025-08705
5. Indicate Type of Lease STATE ☒ FEE ☐
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name Eunice Monument South Unit
8. Well No. 220
9. Pool name or Wildcat Eunice Monument Grayburg S.A.

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well Oil Well ☒ Gas Well ☐ Other ☐	
2. Name of Operator Chevron USA, Inc.	
3. Address of Operator 15 Smith Rd. Midland, Tx 79705	
4. Well Location Unit Letter <u>M</u> <u>3300</u> feet from the <u>South</u> line and <u>600</u> feet from the <u>West</u> line Section <u>6</u> Township <u>21-S</u> Range <u>36-E</u> NMPM County <u>Lea</u>	
10. <u>FR</u> (Show whether DR, RKB, RT, GR, etc.)	

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data			
NOTICE		SUBSEQUENT REPORT OF	
PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☐	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPNS. ☐	PLUG AND ABANDONMENT ☒
PULL OR ALTER CASING ☐	MULTIPLE COMPLETION ☐	CASING TEST AND CEMENT JOB ☐	
OTHER: ☐		OTHER: ☐	

12. Describe proposed completion test or work. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

1. RIH Tag Ctr@3820'(Grayburg, 7" shoe Top of 5" Liner Queen spot 75sx plug fr/3820'to3350' Tag@3336'
2. Displace hole w/MIF 9.5# Brine w/25# Gel p/BBL
3. Perf 4 holes @ 2700' unable to sqz spot 40sx plug fr/2750' to 2600' (B-salt) Tag @ 2463'
4. Perf 4 holes @ 1300' sqz w/75sx fr/1300' to 1150' (9 5/8" shoe, T-salt) Tag @ 1041'
5. Perf 4 holes @ 300' sqz w/110sx fr/300' to surf (12 1/2" shoe) Tag @ 40'
6. Fill 7" csg fr/40' to surf w/10sx Install dry hole marker 8-10-02

Approved as to plugging of the Well Bore.
Liability under bond is retained until
surface restoration is completed.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

Signature: Jimmy D. Bailey TITLE: MANAGER DATE: 8-10-02
Type or print name: JIMMY D. BAILEY / SUNSET Telephone No. 915 520 8756
(This space for State use)

APPROVED BY: GARY W. WINK TITLE: OC FIELD REPRESENTATIVE II / STAFF MANAGER
Conditions of approval of any: GARY W. WINK

GWW

DATE: FEB 05 2003