

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☒ GAS WELL ☒ OTHER		7. UNIT AGREEMENT NAME H-70
2. NAME OF OPERATOR Continental Oil Company		8. FARM OR LEASE NAME Unit B-1
3. ADDRESS OF OPERATOR Box 460, Hobbs, New Mexico		9. WELL NO. 3
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 660' PUL & 1080' PUL, Sec 9-21E-37E, Lea County, New Mexico, N40W.		10. FIELD AND POOL, OR WILDCAT Drinkard (Oil) & Tubb (Gas)
		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec 9-21E-37E
14. PERMIT NO.	15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3496' OF	12. COUNTY OR PARISH Lea
		13. STATE New Mexico

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO :		SUBSEQUENT REPORT OF :	
TEST WATER SHUT-OFF	☐	PULL OR ALTER CASING	☐
FRACTURE TREAT	☐	MULTIPLE COMPLETE	☐
SHOOT OR ACIDIZE	☐	ABANDON*	☐
REPAIR WELL	☐	CHANGE PLANS	☐
(Other)	☐		☐

SUBSEQUENT REPORT OF :	
WATER SHUT-OFF	☐
FRACTURE TREATMENT	☐
SHOOTING OR ACIDIZING	☐
(Other)	☐

Isolate Wells & Reperforate

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) *

The following procedure was used in the isolation of the lower Drinkard perfs & reverberating in the upper Drinkard zone:

- (1) at C19 at 6621' w/24' at cut on top of plug.
- (2) Perforated Brinkard at 6510, 6518, 6555, 6565, 6575, 6586, & 6595' w/1 JSPP.
- (3) Treated peris w/1000 gals 15% LCTM acid, 30,000 gals crude, 30,000# sand, & 1500# "ADMIT" additives.

On 17, will flow 245 lbs oil, no str in 24 hrs w/600 WCFCD.

workover started 5-28-64, completed 5-31-64. Tested 5-31-64.

No change in the T-400 (gas) burner.

18. I hereby certify that the foregoing is true and correct

SIGNED _____ TITLE Assistant District Manager DATE 6-3-64

(This space for Federal or State office use)

APPROVED BY _____ TITLE JUN 9 1964 DATE _____
CONDITIONS OF APPROVAL, IF ANY:

J. L. GORDON

ACTING DISTRICT ENGINEER

***See Instructions on Reverse Side**

USC (5) "HCC" (2) J2 InAs-2000s(5) At1-Pos(2) Calif-4000Mid(1 ea)

Instructions

General: This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

Item 4: If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

Item 17: Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between and above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well site conditioned for final inspection looking to approval of the abandonment.