

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs NM 88240

DISTRICT II
811 S. 1st Street, Artesia, NM 88210-2834

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. <u>30-025-09927</u>
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name <u>Dayton Hardy</u>
8. Well No. <u>1</u>
9. Pool name or Wildcat <u>Penrose Skelly</u> <u>Drinkard Eumont Y-SR-QN</u>
10. Elevation (Show whether DF, RKB, RT, GR, etc.) GL: 3486' KB: 3489'

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. Name of Operator
Marathon Oil Company

3. Address of Operator
P.O. Box 2409, Hobbs, NM 88240

4. Well Location
Unit Letter I : 2310 Feet From The South Line and 330 Feet From The East Line
Section 20 Township 21S Range 37E NMPM Lea County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)
GL: 3486' KB: 3489'

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: Reactivate Grayburg-Eumont ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. ND wellhead. NU BOPE. POOH w/tbg. RIH w/drill collars and 3 1/2" tbg to 3366'. RU Power Swivel. Circ and drill on cement at 3366'. Drilled CIBP at 3410' and pushed to 3614'. POOH.
2. RU bailer and RIH to 3616'. Drill and POOH w/CIBP. RIH w/bailer, bail out sand to 3629'.
3. POOH. RIH w/tbg to 3608'. RIH w/ 3 1/2" tbg to 3608'.
4. NU sub type wellhead in preparation for jet pump.
5. RIH w/ 2 1/16" tbg with jet pump inside 3 1/2" tbg.
6. Hang 2 1/16" tbg off and install surface equipment.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Kelly Cook TITLE _____ DATE Dec. 30, 1996
TYPE OR PRINT NAME Kelly Cook TELEPHONE NO. 393-7106

(This space for State Use)

APPROVED BY _____ TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY:

