

STATE OF NEW MEXICO  
ENERGY AND MINERALS DEPARTMENT

OIL CONSERVATION DIVISION  
P. O. BOX 2088  
SANTA FE, NEW MEXICO 87501

Form C-103  
Revised 10-1-78

|                        |  |
|------------------------|--|
| NO. OF COPIES RECEIVED |  |
| DISTRIBUTION           |  |
| SANTA FE               |  |
| FILE                   |  |
| U.S.O.S.               |  |
| LAND OFFICE            |  |
| OPERATOR               |  |

5a. Indicate Type of Lease  
State ☐ Fee ☒  
5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

|  |  |
|--|--|
| 1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER-<br>2. Name of Operator<br>SHELL OIL COMPANY<br>3. Address of Operator<br>P. O. BOX 991, HOUSTON, TEXAS 77001<br>4. Location of Well<br>UNIT LETTER D 660 FEET FROM THE NORTH LINE AND 660 FEET FROM THE WEST LINE, SECTION 22 TOWNSHIP 21-S RANGE 37-E NMPM.<br>15. Elevation (Show whether DF, RT, GR, etc.)<br>3434' DF | 7. Unit Agreement Name<br>8. Farm or Lease Name<br>ARGO "A"<br>9. Well No.<br>1<br>10. Field and Pool, or Wildcat<br>BLINEBRY OIL & GAS<br>12. County<br>LEA |
|--|--|

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

|  |   |   |   |
|--|---|---|---|
| PERFORM REMEDIAL WORK <input type="checkbox"/> | PLUG AND ABANDON <input type="checkbox"/>   | REMEDIAL WORK <input type="checkbox"/>              | ALTERING CASING <input type="checkbox"/>      |
| TEMPORARILY ABANDON <input type="checkbox"/>   | CHANGE PLANS <input type="checkbox"/>   | COMMENCE DRILLING OPNS. <input type="checkbox"/>    | PLUG AND ABANDONMENT <input type="checkbox"/> |
| PULL OR ALTER CASING <input type="checkbox"/>  | OTHER CLEAN OUT, OPEN ADDITIONAL PAY & ACI-DIZE <input checked="" type="checkbox"/> | CASING TEST AND CEMENT JOB <input type="checkbox"/> | OTHER <input type="checkbox"/>                |

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- Clean out to 5940'. Spot 500 gals double inhibited 15% NE acid.
- Perforate 5 1/2" casing across Blinebry zone 5492' - 5926' (32 holes in 435').
- Set RBP and FBRC at 5933' and 5805'. Acidize Blinebry zone w/14,100 gals 15% NE acid.
- Re-run production equipment and return well to production.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Laddie Curtis A. J. FORE TITLE SUPERVISOR REG. & PERMITTING DATE MARCH 23, 1982  
ORIGINAL SIGNED BY JERRY SEXTON  
APPROVED BY DISTRICT 1 SUPERVISOR DATE MAR 26 1982  
CONDITIONS OF APPROVAL, IF ANY: