Submit 3 Copies to Appropriate
District Office

CONDITIONS OF APPROVAL, IF ANY:

## State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 1-1-89

District Office						
	OIL CONSERVATION		WELL API NO.			
P.O. Box 1980, Hobbs NM 88241-1980 P.O. Box 2088  DISTRICT II Santa Fe, New Mexico 87504-2088			30-025-09932			
P.O. Drawer DD, Artesia, NM 88210			5. Indicate Type	of Lease	FEE X	
DISTRICT III 1000 Rio Brazos Rd., Aztec, NM 87410			6. State Cil & G	******	FEELAI	
SUNDRY NOTICES AND REPORTS ON WELLS  (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"  (FORM C-101) FOR SUCH PROPOSALS.)						
			7. Lease Name or Unit Agreement Name Northeast Drinkard Unit			
1. Type of Well: OIL GAS GAS	<del>- · · · · · · · · · · · · · · · · · · ·</del>		iioi tireda	C DI MIRAI G OM C		
WELL WELL	OTHER	INJECTOR				
2. Name of Operator			8. Well No.			
Shell Western E&P, Inc.  3. Address of Operator	Shell Western E&P, Inc.			91.3W		
	X 77001 Attn: S.A. Gali	k - 5239 WCK	1 '	wndcar e Blinebry-Tubb-C	Orinkard	
4. Well Location Unit Letter K : 1980	Feet From The South	Line and 19	80 Feet Fro	om The West	Line	
Section 23	Township 21S Ra	ange 37E	NMPM	Lon	Country	
	10. Elevation (Show wheth	er DF, RKB, RT, GR, etc	c.)	Lea V////////////////////////////////////	County	
XIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIII	/////	3445' DF				
	copriate Box to Indicate	1	- '		_	
NOTICE OF INTENTION TO: SUB			SEQUEN	REPORT OF	·:	
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK		ALTERING CASING		
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRILLING	OPNS	PLUG AND ABANDON	NMENT [	
PULL OR ALTER CASING		CASING TEST AND CE		1 EGG / HIS / HIS / HIS OF	WALLIA C	
		CASING TEST AND CE			5	
OTHER:		OTHER:	DO Cmt			
<ol> <li>Describe Proposed or Completed Operation work) SEE RULE 1103.</li> </ol>	ons (Clearly state all pertinent det	ails, and give pertinent da	tes, including estin	ated date of starting an	y proposed	
8/31 To 9/16/95						
POOH w/Ini Equip. RI	H w/Csg SWAGE to 5708'.	No tight spot in	csa RTH w/F	RP and PKR Set	ŀ	
RBP @ 5709' and PKR @	5518'. Re-isolate sque	ezed csg leak - no	inj rate. H	Had 600 PSI w/no		
rate. (Communicated	downhole from previous jo	ob.) POH w/ RBP a	nd PKR. RIH	with bit and tag	<b>;</b>	
	ngers to 5936'. DO cmt caving in. Circ hole c					
	tst csg to 500 PSI for 30			:C @ 5425 . CITC	•	
Return well to Inject		, , , , , , , , , , , , , , , , , , , ,	,			
I hereby certify that the information above is true a	and complete to the best of my knowledge	and belief.				
SIGNATURE SHURLEY (1. X	auk m	E Mgr Reg & P	ermitting	DATE	95	
TYPE OR PRINT NAME FOR: G.				TELEPHONE NO. 713/5		
(This space for State Use)					<u> </u>	
This space for State Use)	igNoga og siggyrika №					
APPROVED BY		Œ		S VIII	1 :35	
		***			<del></del>	

