

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs NM 88241-1980

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.	30-025-09932
5. Indicate Type of Lease	STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.	
7. Lease Name or Unit Agreement Name Northeast Drinkard Unit	
8. Well No.	913W
9. Pool name or Wildcat	North Eunice Blinebry-Tubb-Drinkard
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3445' DF	

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/> INJECTOR <input checked="" type="checkbox"/>	2. Name of Operator Shell Western E&P, Inc.
3. Address of Operator P.O. Box 576, Houston, TX 77001 Attn: S.A. Galik - 5239 WCK	4. Well Location Unit Letter <u>K</u> : <u>1980</u> Feet From The <u>South</u> Line and <u>1980</u> Feet From The <u>West</u> Line Section <u>23</u> Township <u>21S</u> Range <u>37E</u> NMPM <u>Lea</u> County
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3445' DF	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: Adjust Injection Profile ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

6/16 To 6/29/95

POOH w/Inj Equip. RIH w/PKR and set @ 6323'. AT Drinkard formation w/4200 gal 20% HCL using 1100# rock salt. Rel PKR. RIH w/RBP and PKR. Set RBP @ 5929. Test tools - held ok. Spot acid across 5739-5886. Reset PKR @ 5693. AT w/4200 gal 20% HCL using 400# rock salt. Reset RBP @ 5709 and PKR @ 5443. POH w/PKR and spot sand on RBP. RIH w/cmt retainer and set @ 5443. Pmp 250 sx CLS C cmt. POH w/tbg. RIH w/4-3/4 bit. Tag TOC @ 5391'. Drilled 52' cmt to retainer, DO ret and 198' cmt. Circ hole cln. RIH w/Guiberson Uni VI PKR and set @ 5698'. Tst csg to 500 PSI for 30 min. (Chart attached). Return well to Injection.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Shirley A. Galik TITLE Mgr. Reg. & Permitting DATE 10/6/95

TYPE OR PRINT NAME For: G. S. Nady TELEPHONE NO. 713/544-4219

(This space for State Use)

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY:

NIGHT

DAY

PRINTED IN U.S.A.

