Form SG104	NE	W MEXICO STATE	LAND OFF	Ъ.			
		SANTA FE, NEW M	IEXICO	الد. -			
, x	DEPARTM	IENT OF THE S Santa fe		OLOGIST			
16	NOTICE (OF INTENTION T					
Notice must be given					-	to the	
ness the plugging	g of wells being a advisable, a copy	that a representative bandoned whenever y of this notice show r. Submit this notice	e of the Der possible.] ving such c	partment of If changes hanges will	the Stat	e Geolo	gist v Lular
17 13 17 m		Hobbs		, N. M	lex., 6 -1	7-34]
Mr. B.H. Wolls Sauta Fe N	Jew Mexico.	<u>.</u>					
Dear Sir:	iew mexico.						
	notified that it is	our intention to ab	andon	8 • • • •			
No in	of Se		andon	318.10	- B-		
N. M. P. M.,			зес д	1 Tee	~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~	, R	
							Co
We plan to commence		on the well are as f		······,	19	····•	
	erating expe		T.D.of				
	arsering exbe	11808.					
	arsering exbe	11808.					- 7 1 <u>-</u> <u>-</u> <u>-</u> <u>-</u>
The present cond	lition of the well i	s as follows:	T.D.of	Well is	3836		
The present cond The work which	ition of the well i	11808.	T.D.of	well is as follows	3836	feet	· ·
The present cond	ition of the well i	do in abandoning	T.D.of	well is as follows	3836	feet	· ·
The present cond The work which Cener with mud.	ition of the well in we propose to	do in abandoning	T.D.of	well is as follows	3836	feet	· ·
The present cond The work which Cener with mud.	ition of the well i	do in abandoning	T.D.of	well is as follows	3836	feet	· ·
The present cond The work which Cener with mud.	ition of the well in we propose to at producing	do in abandoning	T.D.of	well is as follows	3836	feet	· ·
The present cond The work which Cener with mud.	ition of the well in we propose to	do in abandoning formation, p	T.D.of	well is as follows	3836	feet	· ·
The present cond The work which Cener ith and. JUN	ition of the well in we propose to at producing	do in abandoning formation, p	T.D.of the well is will all	well is as follows casing	3836	feet	10 1 8
The present cond The work which Cener with mud.	ition of the well in we propose to at producing	do in abandoning formation, p	T.D.of the well is mll all rely yours,	well is as follows casing	3836	feet 411 }	10 19
The present cond The work which Cener ith and. JUN	ition of the well in we propose to at producing	do in abandoning formation, p . I E. 	T.D.of the well is mall all rely yours, mpire Ga	well is as follows casing	3836	feet	lo 1¢
The present cond The work which Cener ith and. JUN	ition of the well in we propose to at producing	do in abandoning formation, p i i i sincer 	T.D.of the well is mall all rely yours, mpire Ga on Sup'f	well is as follows casing	3836	feet	00 1.6
The present cond The work which Cener ith and. JUN	ition of the well in we propose to at producing	do in abandoning formation, p i i i Sincer B By Position	T.D.of the well is mall all rely yours, mpire Ga	well is as follows casing as &nFue b. Productions regar	3836	feet	Opera Opera

۰.