

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	
A-1375	

## SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input checked="" type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER		7. Unit Agreement Name
2. Name of Operator Me-Tex Supply Company		8. Farm or Lease Name Wallace State
3. Address of Operator P.O. Box 2070 Hobbs, New Mexico 88240		9. Well No. 5
4. Location of Well UNIT LETTER <u>M</u> <u>2990</u> FEET FROM THE <u>South</u> LINE AND <u>660</u> FEET FROM THE <u>West</u> LINE, SECTION <u>3</u> TOWNSHIP <u>21S</u> RANGE <u>36E</u> NMPM.		10. Field and Pool, or Wildcat
15. Elevation (Show whether DF, RT, GR, etc.) 3562' DF		12. County Lea

16.

### Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

#### NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>

#### SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <u>Repair at wellhead leak</u> <input checked="" type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1708.

- 3/10/75 Move Baber Well Service unit to location and rig up. Pull 7/8" & 3/4" rods w/2" x 1-1/4" x 16' pump. Pick up on 2-3/8" tbg. and 6" - 600 x 8" - 600 head. Install secondary seal around 5-1/2" cut off and in 8" - 600 head. Land head and install pressure gauges in 5-1/2" and 8-5/8" csgs. 18 hr. build up 300# on 5-1/2" csg. and 20# on 8-5/8" csg.
- 3/11/75 Bleed down csg. and tbg. and go in hole w/2" x 1-1/4" x 16' pump on 173 - 3/4" and 76 - 7/8" rods. Hang on pumping unit and start pumping at 10:00 A.M. 3/11/75. Have pump action. Well did not pump up.
- 3/13/75 Lower polish rod and bump bottom w/pump. Load tbg. w/16 bbls. oil. Well pressures up and starts pumping.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>Mary Alice Mason</u>	TITLE <u>Secretary</u>	DATE <u>3-25-75</u>
APPROVED BY <u>John</u>	TITLE	DATE

RECEIVED

MAY 2 1978

CH. CANCELLATION UNIT  
UNITED STATES