

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE*
(Other instructions on re-
verse side)

Budget Bureau No. 1004-0135
Expires August 31, 1985
LEASE DESIGNATION AND SERIAL NO.

NM-2512

SUNDRY NOTICES AND REPORTS ON WELLS 88240

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐
2. NAME OF OPERATOR
CONOCO INC.
3. ADDRESS OF OPERATOR
P. O. Box 460, Hobbs, N.M. 88240
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface

6. IF INDIAN, ALLOTTEE OR TRIBE NAME
7. UNIT AGREEMENT NAME
NMEU
8. FARM OR LEASE NAME
Hawk B-1
9. WELL NO.
No. 13
10. FIELD AND POOL, OR WILDCAT
Bluebry / Drinkard
11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

14. PERMIT NO.
API #30-025-20178
15. ELEVATIONS (Show whether DF, RT, GR, etc.)
1980' FSL & 660' FEL

12. COUNTY OR PARISH
Lea
13. STATE
NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF
FRACTURE TREAT
SHOOT OR ACIDIZE
REPAIR WELL
(Other) 1

PULL OR ALTER CASING
MULTIPLE COMPLETE
ABANDON*
CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF
FRACTURE TREATMENT
SHOOTING OR ACIDIZING
(Other) mill pkr & acidize

REPAIRING WELL
ALTERING CASING
ABANDONMENT*

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

MIRU. Set RBP @ 4000'. Set pkr & test csg to 1500 psi for 15 mins; held OK. Rel pkr & RBP. Mill out pkr @ 6535'. CO to 6696'. CO to PBD. Set RBP @ 6700'. Spot acid, open RFC valve & pump 5 bbls pad acid. Rel pkr & reset @ 6500'. Pmpd 120 bbls 15% HCL-FE acid in 3 equal stages. Ran 300# rock salt. Diwab Drinkard. Set RBP @ 6100' & pkr @ 5735'. Acidize Bluebry w/200 bbls pad acid (75% acid, 25% xylene) in 3 stages. Ran prod. equipment. Pmpd. 1980, 39 BW & 287 mcf on 6/1/85.

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE Administrative Supervisor

DATE

7/11/85

(This space for Federal or State office use)

APPROVED BY

ACCEPTED FOR RECORD

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

JUL 15 1985

*See Instructions on Reverse Side

CARLSBAD, NEW MEXICO

RECEIVED

JUL 17 1989

LIBRARY