

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-

5a. Indicate Type of Lease	
State ☒	Fee ☐
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐		7. Unit Agreement Name
2. Name of Operator SHELL WESTERN E&P INC.		NORTHEAST DRINKARD UNIT
3. Address of Operator P. O. BOX 576, HOUSTON, TX 77001 (WCK 4435)		8. Farm or Lease Name NORTHEAST DRINKARD UNIT
4. Location of Well UNIT LETTER <u>A</u> <u>660</u> FEET FROM THE <u>NORTH</u> LINE AND <u>660</u> FEET FROM THE <u>EAST</u> LINE, SECTION <u>15</u> TOWNSHIP <u>21S</u> RANGE <u>37E</u> N.M.P.M.		9. Well No. 612
15. Elevation (Show whether DF, RT, GR, etc.) 3444' GR		12. County LEA

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data.
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐
PULL OR ALTER CASING ☐	OTHER <u>SOZ, OAP & ACDZ</u> ☒

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐	ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐	PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐	OTHER ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. POH w/prod equip.
2. Set pkr @ 6400'.
3. Sqz Drinkard perms 6517'-39' w/50 sx Cls "C" cmt + .3% D60 followed by 50 sx Cls "C" cmt + 2% CaCl₂.
4. Reset pkr @ 5700'.
5. Sqz Blinebry perms 5795' - 5907' w/100 sx Cls "C" cmt + .3% D60 followed by 50 sx Cls "C" cmt + 2% CaCl₂. POH w/pkr.
6. DO cmt to 6545'. Pres tst sqz to 500#.
7. DO cmt cap + CIBP @ 6559'. CO to 6690'.
8. Run GR/CCL log from TD to 5450'.
9. Perf Blinebry 5787' - 6002' & Drinkard 6435' - 6668' (1 JSPF).
10. Acdz perms 5787' - 6668' w/10,920 gals 15% HCl-NEA + 1750# rock salt.
11. Install prod equip & return well to prod.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>A. J. FORE</u>	TITLE <u>SUPERVISOR REG. & PERMITTING</u>	DATE <u>3-09-88</u>
ORIGINAL SIGNED BY JERRY SEXTON DISTRICT I SUPERVISOR		
APPROVED BY _____	TITLE _____	DATE _____
CONDITIONS OF APPROVAL, IF ANY:		

MAR 14 1988

RECEIVED

MAR 1 1 1988

OCD

HOBBS OFFICE