

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-71

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease
State ☒ Fee ☐

5. State Oil & Gas Lease No.
B-1732

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐	7. Unit Agreement Name
2. Name of Operator <u>DOUG GRIMES</u>	8. Farm or Lease Name <u>SUNSHINE STATE</u>
3. Address of Operator <u>1303 E. 15TH ST., MONAHANS, TEXAS 79756</u>	9. Well No. <u>1</u>
4. Location of Well UNIT LETTER <u>C</u> <u>990</u> FEET FROM THE <u>NORTH</u> LINE AND <u>2209</u> FEET FROM THE <u>WEST</u> LINE, SECTION <u>19</u> TOWNSHIP <u>21S</u> RANGE <u>37E</u> NMPM.	10. Field and Pool, or Wildcat/ <u>PENROSE SKELLY/</u> <u>BLINEBRY/DRINKARD</u>
11. Elevation (Show whether DF, RT, GR, etc.) <u>3532' KB</u>	12. County <u>LEA</u>

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☒	PLUG AND ABANDON ☐	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPNS. ☐	PLUG AND ABANDONMENT ☐
PULL OR ALTER CASING ☐	OTHER ☐	CASING TEST AND CEMENT JOB ☐	OTHER ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

IN 1976 A WORKOVER WAS ATTEMPTED ON THIS WELL AND FAILED BECAUSE OF STUCK TUBING AND RODS. THE WELL WAS T/A AT THAT TIME. THIS WELL HAD BEEN PRODUCING FROM BLINEBRY PERFS. 5674 - 5730'; DRINKARD PERFS 6657-6696'; AND PENROSE SKELLY PERFS 3803-3853' (COMMINGLED)

PROPOSED WORKOVER:

1. MIRV PU. NUBOP. DETERMINE FREE POINT OF TUBING.
2. RUN IMPRESSION BLOCK IN TBG TO DETERMINE ROD FISH CONFIGURATION
3. RUN 3425' - 3/4" RODS AND TIE ON TO FISH. (OVER)

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Doug Grimes TITLE Owner DATE 2-21-86

ORIGINAL SIGNED BY JERRY SEXTON

APPROVED BY DISTRICT SUPERVISOR TITLE DATE MAR 10 1986

CONDITIONS OF APPROVAL, IF ANY:

4. BACK ROPE OFF AS DEEP AS POSSIBLE.
5. RUN IN HOLE WITH TBG CUTTER AND CUT OFF AS DEEP AS POSSIBLE.
6. RUN IN HOLE WITH MILL, WASHPIPE, OVERSHOT AND JARS.
7. MILL AND CLEAN OUT TO 6770' (TD) PULL OUT OF HOLE
8. RUN LOGS FROM 6770' TO 3500'.
9. RUN TBG AND PKR TO APPROX 5300' TO TEST DRINKARD AND BLINEBRY ZONES. POH.
10. PERF. PADDOCK 5160 - 5184'.
11. RIH WITH PKR AND RET. PLUG AND ACIDIZE PADDOCK PERFS.
12. SWAB AND TEST.
13. IF COMMERCIALY PRODUCTIVE IN ALL ZONES, SET PKR AT APPROX. 5500' AND DUALY COMPLETE BLINEBRY - DRINKARD (COMMINGLED) AND PADDOCK ZONES

RECEIVED
FEB 21 1986
O.C.D.
HOBBS OFFICE