

NO. OF COPIES RECEIVED
DISTRIBUTION
SANTA FE
FILE
U.S.G.S.
LAND OFFICE
OPERATOR

NEW MEXICO OIL CONSERVATION COMMISSION
Dec 6 12 03 PM '65

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>	
5. State Oil & Gas Lease No. E-229	
7. Unit Agreement Name	
8. Farm or Lease Name South Wilson Deep Unit	
9. Well No. 1	
10. Field and Pool, or Wildcat South Pennsylvanian Gas	
12. County Lea	

SUNDRY NOTICES AND REPORTS ON WELLS

DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.

1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER <input type="checkbox"/>
2. Name of Operator Sinclair Oil & Gas Company
3. Address of Operator P. O. Box 1920, Hobbs, New Mexico
4. Location of Well UNIT LETTER L 1980 FEET FROM THE South LINE AND 660 FEET FROM West THE LINE, SECTION 23 TOWNSHIP 21S RANGE 34E N.M.P.M.

15. Elevation (Show whether DF, RT, GR, etc.)
3717' GR

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe proposed or completed operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.
PROPOSE TO PLUG AND ABANDON AS FOLLOWS:

Present Depth: 12,915' PB. Perfs. 12,642-12,895'.
13-3/8" casing set at 923' and cement circulated to surface.
9-5/8" casing set at 5600' and cement circulated to surface.
7" casing set at 13,992' and cemented back to 10,695' from surface.

PROPOSE TO: Set cement plugs as follows; with hole full of heavy mud.

10 sacks cement (20' plug) on top of C.I. Bridge Plug set @ 12,640'.
25 sacks cement (100' plug) in top of 7" casing stub.
25 sacks cement (100' plug) 8100-8000' top of Bone Springs.
25 sacks cement (100' plug) bottom of 9-5/8" casing.
10 sacks cement in top of 9-5/8" casing and cellar.
Set regulation Dry Hole Marker.
Clean and Level Location.

I, I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED [Signature] TITLE Superintendent DATE 12-7-65

APPROVED BY [Signature] TITLE DATE

CONDITIONS OF APPROVAL, IF ANY:

Origu2cc: CCC Hobbs, cc: State Land Office, cc: Regional Office, Partners, cc: file