

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	
OG-2304	
7. Unit Agreement Name	
8. Farm or Lease Name	
Humble State	
9. Well No.	
1	
10. Field and Pool, or Wildcat	
Lynch Yates-SR	
12. County	
Lea	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT --" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	2. Name of Operator
	Dan C. Berry
3. Address of Operator	
	c/o Oil Reports & Gas Services, Inc., Box 763, Hobbs, New Mexico 88240
4. Location of Well	
UNIT LETTER <u>P</u> . <u>2970</u> FEET FROM THE <u>South</u> LINE AND <u>990</u> FEET FROM	
THE <u>East</u> LINE, SECTION <u>2</u> TOWNSHIP <u>21 S</u> RANGE <u>33 E</u> NMPM.	
15. Elevation (Show whether DF, RT, GR, etc.)	
	3791 KB

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Plugged and abandoned 2/6/74 as follows:

Set cast iron bridge plug at 3490' & capped with 10 sacks class "C" cement.
Cut & pulled 54 joints 4 1/2" casing (approx 1675').
Set wooden plug with wire line on top of 4 1/2" casing.
Spotted 10 sacks class "C" cement on top of wooden plug.
Cut & pulled 513' of 7" casing.
Set wooden plug with wire line on top of 7" casing stub.
Spotted 10 sacks class "C" cement on top of plug with dump bailer.
Set 5 sack plug at surface with regulation marker.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>John W. Runyan</u>	TITLE <u>Agent</u>	DATE <u>1/23/75</u>
APPROVED BY <u>John W. Runyan</u>	TITLE <u>Agent</u>	DATE <u>1/23/75</u>
CONDITIONS OF APPROVAL, IF ANY:		