

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>

5. State Oil & Gas Lease No.
03-2304

<p align="center">SUNDRY NOTICES AND REPORTS ON WELLS</p> <p align="center"><small>(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)</small></p>		
<p>1. <input checked="" type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER-</p>		7. Unit Agreement Name
<p>2. Name of Operator Dan C. Berry</p>		8. Farm or Lease Name Humble State
<p>3. Address of Operator c/o Oil Reports & Gas Services, Inc., Box 763, Hobbs, N. M. 88240</p>		9. Well No. 1
<p>4. Location of Well UNIT LETTER P 2970 FEET FROM THE South LINE AND 990 FEET FROM THE East LINE, SECTION 2 TOWNSHIP 21 S RANGE 33 E NMPM.</p>		10. Field and Pool, or Wildcat Lynch Yates-SR
<p>15. Elevation (Show whether DF, RT, GR, etc.) 3791 KB</p>		12. County Lea

<p>16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data</p>			
NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

It is proposed to plug for abandonment as follows:

100' plug above perforations 3748-54
To cut and pull 4 1/2" casing with 100' plug
across stub; if recovered below base of Salt
100' plug at base of Salt and 100' plug at top
of Salt.
100' plug across 10 3/4" casing shoe @ 379'.
10 sacks at surface with regulation marker.
Mud between all plugs.
Location to be cleared and levelled.

24 hr. notice

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED *Anna Holke* TITLE Agent DATE 10/27/72

APPROVED BY Orig. Signed by Joe D. Ramey Dist. I, Supv. TITLE _____ DATE 00T 30 1972

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED

OCT 30 1972

OIL CONSERVATION COMM.
HOBBS, N. M.