NO. OF COPIE	S RECEIVED], , ,						
	STRIBUTION C. C.				000	Form C-103 Supersedes Old		
SANTAFE	The state of the s				U. U. U.	C-102 and C-103		
		NEW ME	EXICO OIL CON	SERVATION (COMMISSION	Effective 1	-1-65 ·	
FILE		Orig&2cc: (nobos,	Allew 31eth	19. WA			
U.S.G.S.				Mce	•	5a. Indicate Ty	pe of Lease	
LAND OFFIC	JE	cc:	TITE			State	Fee.	
OPERATOR]				5, State Oil & C	Gas Lease No.	
	CINIDE			•		· · · · · · · · · · · · · · · · · · ·		
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROFOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT —" (POR C-101) FOR SUCH PROPOSALS.)								
1.							7111111111111	
OIL X	GAS WELL	OTHER.				7. Unit Agreem	eut Name	
2. Name of Ope	erator					8. Farm or Lea	se Name	
Sinclair Oil & Gas Company							S. J. Sarkeys	
3. Address of Operator P. O. Box 1920, Hobbs, New Mexico							9. Well No.	
	P. U. BOX 1	.920, Hobbs, I	New Mexico			6		
4. Location of						10. Field and F	Pool, or Wildcat	
UNIT LETTE	J 23	1.0	Sout	n	1980	Warte Abo Drinkard		
		PEET FROM	THE	LINE AND	FEET FROM	mmm'	minim	
Eas	S t	23	218	RANGE _	37E			
182	LINE, SECTIO	JN T	OWNSHIP	RANGE_	НМРМ	MIIIII		
		15, Elevat	ion (Show whether	DF, RT, GR, e	tc.)	12. County	<i>HHHHH</i>	
			330	58' GR		Lea		
16.	Check	Appropriate Box	To Indicate N	lature of No	otice, Report or Ot	1 D		
	NOTICE OF IN	TENTION TO:	To indicate i	vature of Mc				
	1101102 01 11	41 E141 1014 10:			SUBSEQUEN	T REPORT OF	:	
PERFORM REME	DIAL WORK	n	AND ABANDON					
	Ħ	PLUG	AND ABANDON []	REMEDIAL WO	 - 	ALTE	ERING CASING	
TEMPORARILY ABANDON COMMENCE DRILLING OPNS.						PLUG	AND ABANDONMENT	
CHANGE PLANS CASING TEST AND CEMENT JOB OTHER -B PETFORATE & E						ocidina & 9	75	
OTHER					acidize & b	, <u>or</u>		
VINER								
17. L'escribe Pr	roposed or Completed Op	erations (Clearly stat	e all pertinent det	ails, and give p	ertinent dates, including	estimated date o	starting any proposed	
17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date work) SEE RULE 1703. 1-19-67 Set Cast Iron Bridge Plug @ 66501 and dumped 2 sacks cement 6650-6635								
2 2/ 01	Abo formation	6898-73251	e oogo and	t damped 2	sacks cement	0050-00351	and abandoned	
1-20-67	Jet perforate	d Drinkard Al	32_1/3 51 50	75 88 65	603,25,30,38,54	(1 02 ((00	/	
	34-3/8" holes	a Milikala ()	JE-47971977	2000000	00,20,30,54	000,000,0000	/W 'LL و د ا	
1-21-67 Acidized Drinkard perfs. 6432-6611' w/1500 Gals. BDA Max. Press. 4000#, Min. 2							ar. araa#	
	@ 2.7 BPM ISI	P 2500#. 5 mi	ng STP 230	M#	.s. DDA Max. Pr	ess. 4000#,	Min. 2500#,	
1-22-67	Sand Oal Frac	ed Drinkard n	arfa 61.32	Ω#• .6613.1. ++/2	0 000 ====	es 1 . 1 . 1 . 1 . 1	-1.00.000#	
	-22-67 Sand Oil Fraced Drinkard perfs. 6432-6611' w/20,000 gals. refined oil and 20,000# sand Max. Press. 6900#, Min. 6000#@ 12.7 BPM. ISIP 3800#, 5 mins. SIP 3400#.							
	12 hr. SITP 1	800#.	11. 0000# \$	LZe! DFM	ا والمال المالات	5 mins. Sir	3400# _•	
1-28-67			ending 12	Noon 3-28	-67 Flowed Dri		3 30 MIO	
,	no water 21/	Will above To	hing Droces	775#	Cootes & -1 -2	nkaro peris	ONG OCC	
	Completed in	Drinkend nort	. 41.20 441	11 - Ft	Casing Sealed.	GVLY 3/.2	GUR 22211.	
	Brinkard.	or minard ben	8. 0422-001	T. ST cel. o	lepleting Abo at	na prugging	; back to	
	M lindiu							
18, I hereby cert	tify that the information	above is true and com	plete to the best o	f my knowledge	and belief.	· · · · · · · · · · · · · · · · · · ·		
, F-=	<, ,/<							
SIGNED	it then		S	uperinten	dent	DATE 1-3	0-67	
			TITLE			DATE		
_							G CNT	
A B B B O V F D B V							DOT.	

CONDITIONS OF APPROVAL, IF ANY: