

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

# NEW MEXICO OIL CONSERVATION COMMISSION

Orig & 2cc: CCC, Hobbs, New Mex.  
cc: Regional Office  
cc: file

HOBBBS OFFICE 0.1  
Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65  
44-18 11 49 AM '67

5a. Indicate Type of Lease
State <input type="checkbox"/> Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.

## SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator Sinclair Oil & Gas Company	8. Farm or Lease Name Sarkeys
3. Address of Operator P. O. Box 1920, Hobbs, New Mexico	9. Well No. 6
4. Location of Well UNIT LETTER J, 2310 FEET FROM THE South LINE AND 1930 FEET FROM THE East LINE, SECTION 23 TOWNSHIP 21S RANGE 37E N.M.P.M.	10. Field and Pool, or Wildcat Wantz Abo
15. Elevation (Show whether DF, RT, GR, etc.) 3368' GR	12. County Lea

## Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

### NOTICE OF INTENTION TO:

### SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER Plugback & Perf., acidize & SOF <input checked="" type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1703.

Well presently completed in Abo formation perforations 6898-7325'. TD 7370', PBTD 7335'.

PROPOSE TO: Abandon Abo perforations 6898-7325' w/C.I.B.P. set approx. 6630' and 2 sacks cement. Perforate Drinkard formation approx. 6432-6559' and acidize w/approx. 3000 gals. breakdown acid. SOF w/approx. 20,000 gals. refined oil and approx. 20,000# sand and recomplete in Drinkard zone.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNER [Signature] TITLE Superintendent DATE 1-17-67

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_

CONDITIONS OF APPROVAL, IF ANY: