

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPL  
(Other instructions  
verse side)

Budget Bureau No. 1004-0135  
Expires August 31, 1985

5. LEASE DESIGNATION AND SERIAL NO.

LC-031741(a)

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR  
CONOCO INC.

3. ADDRESS OF OPERATOR  
P. O. Box 460, Hobbs, N.M. 88240

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.\*  
See also space 17 below.)  
At surface

1980' FNL & 1980' FEL

7. UNIT AGREEMENT NAME

NMFU

8. FARM OR LEASE NAME

Hawk A

9. WELL NO.

6

10. FIELD AND POOL, OR WILDCAT

Blinberry/Drinkard

11. SEC., T., R., &, OR BLK. AND  
SURVEY OR AREA

Sec 8, T-21S, R-37E

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

12. COUNTY OR PARISH

Lea

13. STATE

NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON\*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other) downhole commingle

REPAIRING WELL

ALTERING CASING

ABANDONMENT\*

(NOTE: Report results of multiple completion on Well  
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

MIRU. POOH w/RBP. CO to 6800'. Set RBP @ 6771' & pkr @ 6463'.  
Acidize Drinkard perfs in 2 equal stages w/total of 45 bbls.  
acid-xylene. Flush w/27 bbls filtered TFW. Inhibit Drinkard perfs.  
Reset RBP @ 6092' & pkr @ 5503'. Acidize Blinberry perfs w/64 bbls  
acid-xylene in 2 stages. Flush w/32 bbls. TFW. Rel RBP & pkr.  
Run prod. equipment w/ SN. @ 6744'. Pmpd. 39 BO, 30 BW  
& 98 MCF on 1/3/85

18. I hereby certify that the foregoing is true and correct

SIGNED

David A. Smylie

TITLE

Administrative Supervisor

DATE

1/23/85

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

PER 7 BBL

\*See Instructions on Reverse Side

RECEIVED

FEB 11 1985

O.C.D.  
HOUSE OFFICE