

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. B-8268	
7. Unit Agreement Name North Wilson Deep Unit	
8. Farm or Lease Name	
9. Well No. 3	
10. Field and Pool, or Wildcat Osudo Morrow	
12. County Lea	

SUNDRY NOTICES AND REPORTS ON WELLS

DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.

1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER <input type="checkbox"/>	2. Name of Operator Gulf Oil Corporation
3. Address of Operator Box 670, Hobbs, N.M. 88240	4. Location of Well UNIT LETTER I 3224 FEET FROM THE north LINE AND 660 FEET FROM THE east LINE, SECTION 6 TOWNSHIP 21S RANGE 35E N.M.P.M.
15. Elevation (Show whether DF, RT, GR, etc.) 3649' GL	

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐
PULL OR ALTER CASING ☐
OTHER ☐

PLUG AND ABANDON ☒
CHANGE PLANS ☐
OTHER ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐
COMMENCE DRILLING OPNS. ☐
CASING TEST AND CEMENT JOBS ☐
OTHER ☐
ALTERING CASING ☐
PLUG AND ABANDONMENT ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

11,525' PB. Kill well with brine water, unseat from packer and circulate brine water out with abandonment mud and spot 20 sx Class C cement from 11,214' to 10,890'. Run free point and cut 4 1/2" casing at approximately 9610' and pull. Spot 30 sx Class C cement across 4 1/2" casing stub and open hole. Spot 30 sx Class C cement plug from 7700' to 7550'. Spot 30 sx Class C cement plug from 5500' to 5325'. Run free point and cut casing (7-5/8") at 3800'. Spot 40 sx Class C cement plug from 3850' to 3725'. Circulate mud to surface. Spot 30 sx Class C cement plug from 50' to surface. Install dry hole marker, clean location.

100' plugs
24 hr. notice

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED K. J. Bragzale TITLE Area Engineer

DATE 4-26-73

APPROVED BY _____
CONDITIONS OF APPROVAL, IF ANY:

TITLE _____ DATE _____