NO. OF COPIES RECEIVED		
FISTRIBUTION		Form C -103
		Supersedes Old C-102 and C-103
SANTAFE	NEW MEXICO OIL CONSERVATION COMMISSION	Effective 1-1-65
FILE		2
U.S.G.S.	——————————————————————————————————————	5a. Indicate Type of Lease
AND OFFICE		
DPERATOR		
		5. State Oil & Gas Lease No.
<u> </u>		B-1439
DO NOT USE THIS FORM FOR	DRY NOTICES AND REPORTS ON WELLS PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. CATION FOR PERMIT -** (FORM C-101) FOR SUCH PROPOSALS.	
USE "APPLIC	CATION FOR PERMIT (FORM C-101) FOR SUCH PROPOSALS.)	(1)
01_ GAS		7. Unit Agreement Name
WELL WELL	07HER-	North Wilson Deep Unit
Name of Operator		8. Farm or Lease Name
The British-American	Oil Producing Company	
Address of Operator		North Wilson Deep Unit
P. O. Box 474	Midland, Texas	9. WEIT NO.
Location of Well	nitially, leads	3
•	2004	10. Field and Pool, or Wildcat
UNIT LETTER	3224 FEET FROM THE NOTTH LINE AND 660 FEET	FROM Undesignated
THE CASE LINE, SEC	TICN 6 TOWNSHIP 21-S RANGE 35-E N	
	RANGE N	амрм. Д////////////////////////////////////
///////////////////////////////////////	15. Elevation (Show whether DF, RT, GR, etc.)	
	3649' GL, 3663' KB	12. County
NOTICE OF	Appropriate Box To Indicate Nature of Notice, Report or	· Other Data IENT REPORT OF:
	0000200	ENT REFORT OF:
REORM REMEDIAL WORK	PLUG AND ABANDON REMEDIAL WORK	
	PLUS AND ABANDON REMEDIAL WORK	ALTERING CASING
MPOFARILY ABANDON	COMMENCE DRILLING OPNS.	ALTERING CASING
MPOFARILY ABANDON	COMMENCE DRILLING OPNS.	PLUG AND ABANDONMENT
MPOFARILY ABANDON	COMMENCE DRILLING OPNS.	PLUG AND ABANDONMENT
MPOFARILY ABANDON	COMMENCE DRILLING OPNS.	PLUG AND ABANDONMENT
Describe Proposed or Completea work) SEE RULE (1103, Set 40 sx cement plu	CHANGE PLANS COMMENCE DRILLING OPNS. CHANGE PLANS CASING TEST AND CEMENT JOB X OTHER <u>Set whipsto</u> Operations (Clearly state all pertinent details, and give pertinent dates, inclu	PLUG AND ABANDONMENT
ACCORDANCE AND A CONTRACT AND A CONT	CHANGE PLANS CHANGE PLANS CHANGE PLANS CHANGE PLANS CASING TEST AND CEMENT JOB OTHER <u>Set whipsto</u> OTHER <u>Set whipsto}</u> OTHER <u>SET WHI</u>	PLUG AND ABANDONMENT
MPOFARILY ABANDON DILL OF ALTER CASING OTHER Describe Proposed or Completed WORK) SEE RULE 1103. Set 40 sx cement plu Set 9-5/8" OD, 36#, tool at 2966'. Ceme Kolite per sx. Open 10% salt and 150 sxs 1:00 p.m., 6-26-66. Held okay. Drilled casing shoe and 1% T.I.C. from 3 Dressed off plug wit Drilled 6-3/4" pilot No allowable will be directional drilling The utilization of a is set at random. I hereby certify that the informatio	CHANGE PLANS CHANGE PLANS CHANGE PLANS COMMENCE DRILLING OPNS. CASING TEST AND CEMENT JOB OTHER <u>Set whipsto</u> OTHER <u>Set whipsto</u> Commented set of the set of	PLUG AND ABANDONMENT