

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

JUL 5 11 38 AM '66

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. E-7825

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <input type="checkbox"/>	7. Unit Agreement Name None
2. Name of Operator Charles B. Read	8. Farm or Lease Name Sinclair State
3. Address of Operator Box 1822, Roswell, New Mexico	9. Well No. 2
4. Location of Well UNIT LETTER V , 2310 FEET FROM THE West LINE AND 990 FEET FROM THE South LINE, SECTION 2 TOWNSHIP 21S RANGE 33E NMPM.	10. Field and Pool, or Wildcat Lynch
15. Elevation (Show whether DF, RT, GR, etc.) 3808' GL	12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Propose to plug and abandon on 7/8/66 per verbal authority. Cement plugs will be set as follows:

25 sx @ 3775-3875' TD;
25 sx 3460-3560', B/Salt;
25 sx 1900-2000', T/Salt;
25 sx 340-440', B/surface csg. ;
10 sx @ surface.

Heavy mud will be spotted between plugs. Will install dry hole marker, fill pits, level and clean location, and restore surface area.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>Charles B. Read</u>	TITLE <u>Operator</u>	DATE <u>7/5/66</u>
APPROVED BY <u>[Signature]</u>	TITLE <u></u>	DATE <u></u>

CONDITIONS OF APPROVAL, IF ANY: