DISTRIBUTION	Form C-103
	Supersedes Old C-102 and C-103
FILE NEW MEXICO OIL CONSERVATION COMMISSION	Effective 1-1-65
	5a. Indicate Type of Lease
AND OFFICE 55 IN SQ	State Fee.
OPERATOR 0J	5. State Oil & Gas Lease No.
SUNDRY NOTICES AND DEPODTS ON WELLS	
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROFOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)	
OIL X GAS WELL OTHER-	7. Unit Agreement Name None
Name of Operator APCO OIL CORPORATION	8. Farm or Lease Name
Address of Operator	Currie
Liberty Bank Building, Oklahoma City, Oklahoma	9. Well No. 2
Location of Well	10. Field and Pool, or Wildcat
UNIT LETTER L 670 FEET FROM THE West LINE AND 3310 FEET	FROM
THE North Line, section 5 TOWNSHIP 215 RANGE 37E	
	^{мрм.} (////////////////////////////////////
15. Elevation (Show whether DF, RT, GR, etc.)	12. County
11111111111111111111111111111111111111	Lea
Check Appropriate Box To Indicate Nature of Notice, Report or	Other Data
NOTICE OF INTENTION TO: SUBSEQU	ENT REPORT OF:
PLUG AND ABANDON REMEDIAL WORK	
EMPORARILY ABANDON COMMENCE DRILLING OPNS.	ALTERING CASING
CHANGE PLANS CHANGE PLANS CASING TEST AND CEMENT JOB	PLUG AND ABANDONMENT
OTHER	
OTHER	
OTHER	
Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, incluwork) SEE RULE 1103. Ran 123 joints 5 ¹ / ₂ " OD K-55 Production Casing	ding estimated date of starting any propo
Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, inclu- work) SEE RULE'1103. Ran 123 joints 5 ¹ / ₂ " OD K-55 Production Casing. Threads off length 3890'. Cemented with 125 sx. Class C Cement 50/50 Poz-mix, 6% gell per sx., followed by 150 sx. Class C neat. Plug down 9:10 AM, Oct slips and cut off. No water lost from casing in 48 hours. OK	ding estimated date of starting any propo 3909.21. Set @ ., w/1/4# Cello-flakes
Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, inclu work) see RULE 1103. Ran 123 joints 5 ¹ / ₂ " OD K-55 Production Casing. Threads off length 3890'. Cemented with 125 sx. Class C Cement 50/50 Poz-mix, 6% gel per sx., followed by 150 sx. Class C neat. Plug down 0:10 AV 0:00	ding estimated date of starting any propo 3909.21. Set @ ., w/1/4# Cello-flakes
Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, inclu work) SEE RULE 1103. Ran 123 joints 5 ¹ / ₂ " OD K-55 Production Casing. Threads off length 3890'. Cemented with 125 sx. Class C Cement 50/50 Poz-mix, 6% gell per sx., followed by 150 sx. Class C neat. Plug down 9:10 AM, Oct slips and cut off. No water lost from casing in 48 hours. OK	ding estimated date of starting any propo 3909.21. Set @ ., w/1/4# Cello-flakes
Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, inclu- work) SEE RULE'1103. Ran 123 joints 5 ¹ / ₂ " OD K-55 Production Casing. Threads off length 3890'. Cemented with 125 sx. Class C Cement 50/50 Poz-mix, 6% gell per sx., followed by 150 sx. Class C neat. Plug down 9:10 AM, Oct slips and cut off. No water lost from casing in 48 hours. OK	ding estimated date of starting any propo 3909.21. Set @ ., w/1/4# Cello-flakes
Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, inclu work) SEE RULE 1703. Ran 123 joints 5 ¹ / ₂ " OD K-55 Production Casing. Threads off length 3890'. Cemented with 125 sx. Class C Cement 50/50 Poz-mix, 6% gell per sx., followed by 150 sx. Class C neat. Plug down 9:10 AM, Oct slips and cut off. No water lost from casing in 48 hours. OK	ding estimated date of starting any propo 3909.21. Set @ ., w/1/4# Cello-flakes
Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, inclu work) SEE RULE 1703. Ran 123 joints 5 ¹ / ₂ " OD K-55 Production Casing. Threads off length 3890'. Cemented with 125 sx. Class C Cement 50/50 Poz-mix, 6% gell per sx., followed by 150 sx. Class C neat. Plug down 9:10 AM, Oct slips and cut off. No water lost from casing in 48 hours. OK	ding estimated date of starting any propo 3909.21. Set @ ., w/1/4# Cello-flakes
Ban 123 joints 5 ¹ / ₂ " OD K-55 Production Casing. Threads off length 3890'. Cemented with 125 sx. Class C Cement 50/50 Poz-mix, 6% gell per sx., followed by 150 sx. Class C neat. Plug down 9:10 AM, Octal slips and cut off. No water lost from casing in 48 hours. OK	ding estimated date of starting any propo 3909.21. Set @ ., w/1/4# Cello-flakes
Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, inclu work) SEE RULE 1703. Ran 123 joints 5 ¹ / ₂ " OD K-55 Production Casing. Threads off length 3890'. Cemented with 125 sx. Class C Cement 50/50 Poz-mix, 6% gell per sx., followed by 150 sx. Class C neat. Plug down 9:10 AM, Oct slips and cut off. No water lost from casing in 48 hours. OK	ding estimated date of starting any propo 3909.21. Set @ ., w/1/4# Cello-flakes
Ban 123 joints 5 ¹ / ₂ " OD K-55 Production Casing. Threads off length 3890'. Cemented with 125 sx. Class C Cement 50/50 Poz-mix, 6% gell per sx., followed by 150 sx. Class C neat. Plug down 9:10 AM, Octal slips and cut off. No water lost from casing in 48 hours. OK	ding estimated date of starting any propo 3909.21. Set @ ., w/1/4# Cello-flakes
Ban 123 joints 5 ¹ / ₂ " OD K-55 Production Casing. Threads off length 3890'. Cemented with 125 sx. Class C Cement 50/50 Poz-mix, 6% gell per sx., followed by 150 sx. Class C neat. Plug down 9:10 AM, Octal slips and cut off. No water lost from casing in 48 hours. OK	ding estimated date of starting any propo 3909.21. Set @ ., w/1/4# Cello-flakes
Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, incluwork) SEE RULE 1103. Ran 123 joints 5 ¹ / ₂ " OD K-55 Production Casing. Threads off length 3890'. Cemented with 125 sx. Class C Cement 50/50 Poz-mix, 6% gell per sx., followed by 150 sx. Class C neat. Plug down 9:10 AM, Octables and cut off. No water lost from casing in 48 hours. OK	ding estimated date of starting any propo 3909.21. Set @ ., w/1/4# Cello-flakes
Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, inclu work) SEE RULE 1103. Ran 123 joints 5 ¹ / ₂ " OD K-55 Production Casing. Threads off length 3890'. Cemented with 125 sx. Class C Cement 50/50 Poz-mix, 6% gell per sx., followed by 150 sx. Class C neat. Plug down 9:10 AM, Oct slips and cut off. No water lost from casing in 48 hours. OK	ding estimated date of starting any propo 3909.21. Set @ ., w/1/4# Cello-flakes
Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, inclu- work) SEE RULE'1103. Ran 123 joints 5 ¹ / ₂ " OD K-55 Production Casing. Threads off length 3890'. Cemented with 125 sx. Class C Cement 50/50 Poz-mix, 6% gell per sx., followed by 150 sx. Class C neat. Plug down 9:10 AM, Oct slips and cut off. No water lost from casing in 48 hours. OK	ding estimated date of starting any propo 3909.21. Set @ ., w/1/4# Cello-flakes
Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, inclu work) SEE RULE 1103. Ran 123 joints 5 ¹ / ₂ " OD K-55 Production Casing. Threads off length 3890'. Cemented with 125 sx. Class C Cement 50/50 Poz-mix, 6% gell per sx., followed by 150 sx. Class C neat. Plug down 9:10 AM, Oct slips and cut off. No water lost from casing in 48 hours. OK	ding estimated date of starting any propo 3909.21. Set @ ., w/1/4# Cello-flakes
Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, inclu work) SEE RULE 1103. Ran 123 joints 5½" OD K-55 Production Casing. Threads off length 3890'. Cemented with 125 sx. Class C Cement 50/50 Poz-mix, 6% gel per sx., followed by 150 sx. Class C neat. Plug down 9:10 AM, Oct slips and cut off. No water lost from casing in 48 hours. OK. The bond log.	ding estimated date of starting any propo 3909.21. Set @ ., w/1/4# Cello-flakes
Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, inclu work) SEE RULE 1103. Ran 123 joints 5½" OD K-55 Production Casing. Threads off length 3890'. Cemented with 125 sx. Class C Cement 50/50 Poz-mix, 6% gel per sx., followed by 150 sx. Class C neat. Plug down 9:10 AM, Oct slips and cut off. No water lost from casing in 48 hours. OK. The bond log.	ding estimated date of starting any propo 3909.21. Set @ ., w/1/4# Cello-flakes
I hereby certify that the information above is true and complete to the best of my knowledge and belief. I hereby certify that the information above is true and complete to the best of my knowledge and belief.	ding estimated date of starting any propo 3909.21. Set @ ., w/1/4# Cello-flakes ober 27, 1969. Set op of cement 2572' by
Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, inclu work) SEE RULE 1763. Ban 123 joints 5 ¹ / ₂ " OD K-55 Production Casing. Threads off length 3890'. Cemented with 125 sx. Class C Cement 50/50 Poz-mix, 6% gel per sx., followed by 150 sx. Class C neat. Plug down 9:10 AV, Oc- slips and cut off. No water lost from casing in 48 hours. OK. The bond log.	ding estimated date of starting any propo 3909.21. Set @ ., w/1/4# Cello-flakes ober 27, 1969. Set op of cement 2572' by
Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, inclu work) SEE RULE 1703. Ran 123 joints 5 ¹ / ₂ " OD K-55 Production Casing. Threads off length 3890'. Cemented with 125 sx. Class C Cement 50/50 Poz-mix, 6% gel per sx., followed by 150 sx. Class C neat. Plug down 9:10 AM, Oct slips and cut off. No water lost from casing in 48 hours. OK. The bond log.	ding estimated date of starting any propo 3909.21. Set @ ., w/1/4# Cello-flakes cober 27, 1969. Set lop of cement 2572' by

۰.

র - - - -