

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPPLICATE
(Other instructions on re-
verse side)

Form approved
Budget Bureau No. 045322
5. LEASE DELEGATION AND SERIAL NO.
Federal IC-056522
6. IF INDIAN, ALLOTTEE OR TRUST NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR
Natural Resources Group, Inc.

3. ADDRESS OF OPERATOR
601 George #110, Midland, Texas 79701

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below.)
At surface
Unit Letter D, 990' from the North line and 330'
from the West line of the Section.

14. PERMIT NO.

15. ELEVATIONS (Show whether LF, RT, GR, etc.)
3530' GL

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME
Anna Federal

9. WELL NO.
1

10. FIELD AND POOL, OR WITH
Blaineby

11. SEC., T., R., M., OR B.R. AND
SURVEY OR AREA
Sec. 1-218-37E
Lot 4

12. COUNTY OR PARISH 13. STATE
Lea N.M.

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF	☐	PULL OR ALTER CASING	☐
FRACTURE TREAT	☐	MULTIPLE COMPLETE	☐
SHOOT OR ACIDIZE	☐	ABANDON*	☐
REPAIR WELL	☐	CHANGE PLANS	☐
(Other)	☐	(Other)	☐

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting a proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) *

This well was originally completed as an Abo and Blaineby producing well. 4-5-70: Ran an isolation packer assembly and set it from 5923' to 6073' to shut off Blaineby casing perforations from 5938' to 6040' as the Blaineby zone was no longer economical to produce. the well now only produces from the Abo formation and has a "stripper" classification.

When the Abo formation becomes uneconomical to produce, it will be plugged off and abandoned and the Blaineby zone will then be reopened for further stimulation and testing for possible future production.

18. I hereby certify that the foregoing is true and correct

SIGNED C. J. Egan TITLE Agent DATE 10-28-74

(This space for Federal or State office use)

APPROVED BY _____ TITLE _____
CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side

