

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department
OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

Form C-103
Revised 1-1-89

DISTRICT I

P.O. Box 1980, Hobbs, NM 88240

DISTRICT II

P.O. Drawer Dd, Artesia, NM 88210

DISTRICT III

1000 Rio Brazos Rd., Aztec, Nm 87410

API NO. (assigned by OCD on New Wells)

30-025-23543

5. Indicate Type of Lease

STATE ☐

FEE ☒

6. State Oil & Gas Lease No.

N/A

7. Lease Name or Unit Agreement Name

MOORE

8. Well No.

1

9. Pool name or Wildcat

BLINEBRY

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:

OIL

GAS

WELL ☒

WELL ☐

OTHER

2. Name of Operator

CHEVRON U.S.A. INC.

3. Address of Operator

P.O. BOX 1150 MIDLAND, TX 79702 ATTN: P.R. MATTHEWS

4. Well Location

Unit Letter

I

1980

Feet From The

SOUTH

Line and

410

Feet From The

EAST

Line

Section

25

Township

21S

Range

36E

NMPM

LEA

County

10. Elevation(Show whether DF, RKB, RT, GR, etc.)

11 Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK

☐

PLUG AND ABANDON

☒

TEMPORARILY ABANDON

☐

CHANGE PLANS

☐

PULL OR ALTER CASING

☐

OTHER:

☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK

☐

COMMENCE DRILLING OPNS.

☐

CASING TEST AND CMT JOB

☐

OTHER:

☐

ALTER CASING

☐

PLUG AND ABAN.

☐

12. Describe Proposed or Completed Operations(Clearly state all pertinent details, and give pertinent dates, including
estimated date of starting any proposed work) SEE RULE 1103.

IT IS PROPOSED TO PLUG AND ABANDON.

SET CIBP AT 5470 AND CAP WITH 35' OF CEMENT. SET BALANCED PLUG F/5260-5010 (25 SXS CMT).

ABOVE PLUG WILL COVER GLORIETA AND PADDOCK FORMATION.

SET 40 SX. CMT PLUG F/4040-3630, PLUG WILL COVER GRAYBURG AND SAN ANDRES.

PERF SQZ. HOLES AT 270 SET CIBP AT 2600 & SQZ. W/90 SXS. CMT. LEAVE 35' CMT ON TOP.

ABOVE PLUG WILL COVER YATES AND 8 5/8" SHOE.

SET CIBP AT 1165', SQZ WITH 80 SXS. CMT. LEAVE 35' CMT ON TOP. PLUG COVERS RUSTLER AND TOP OF SALT.

SHOOT SQUEEZE HOLES AT 355' PUMP 150 SXS. CEMENT INTO ANNULUS. LEAVING 5 1/2" CSG. FULL.

CUT OFF WELLHEAD AND INSTALL P & A MARKER.

P & A MUD WILL BE CIRCULATED BETWEEN ALL PLUGS.

P & A MUD = 10#, PLUGS = CLASS "C".

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

P.R. Matthews

TITLE

TECH. ASSISTANT

DATE: 7-15-92

TYPE OR PRINT NAME

P.R. MATTHEWS

TELEPHONE NO. (915)687-7812

APPROVED BY

Orig. Signed by
Paul Kautz
Geologist

TITLE

DATE

JUL 20 '92

CONDITIONS OF APPROVAL: 1. ANY

THE COMMISSION MUST BE NOTICED 24
HOURS PRIOR TO THE BEGINNING OF
PLUGGING OPERATIONS FOR THE C-103
TO BE APPROVED.