

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease
State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.
<b>K-4126-1</b>

## SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER- <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator <b>TEXACO Inc.</b>	8. Farm or Lease Name <b>New Mexico 'DO' St. NCT-1</b>
3. Address of Operator <b>P.O. Box 728, Hobbs, New Mexico 88240</b>	9. Well No. <b>1</b>
4. Location of Well UNIT LETTER <b>J</b> <b>1980</b> FEET FROM THE <b>South</b> LINE AND <b>1980</b> FEET FROM THE <b>East</b> LINE, SECTION <b>18</b> TOWNSHIP <b>21-S</b> RANGE <b>35-E</b> NMPM.	10. Field and Pool, or Wildcat <b>Undesignated</b>
15. Elevation (Show whether DF, RT, GR, etc.) <b>3,669' GR</b>	12. County <b>Lea</b>

16.

### Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

#### NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>

#### SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>



17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

**TEXACO Inc. proposes to Plug and Abandon subject well as follows:**

1. Set CI bridge plug at 12,020'. Cap w/5 sx cement.
2. Cut 5-1/2" casing @5,355' and retrieve same.
3. Spot cement plug from 5,290' to 5,415'.
4. Spot 10 sx cement plug at surface.
5. Set 4" dry hole marker extending 4' above ground level.
6. Clean location.

**Verbal approval from New Mexico Oil Commission received January 27, 1971.**

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED 	TITLE <b>Assistant District Superintendent</b>	DATE <b>February 2, 1971</b>
APPROVED BY 	TITLE <b>SUPERVISOR DISTRICT</b>	DATE <b>FEB 3 1971</b>
CONDITIONS OF APPROVAL, IF ANY.		

RECEIVED

FEB 3 1971

OIL CONSERVATION COMM.

HOUSTON, TEXAS