

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department
OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

Form C-103
Revised 1-1-89

DISTRICT I

P.O. Box 1980, Hobbs, NM 88240

DISTRICT II

P.O. Drawer Dd, Artesia, NM 88210

DISTRICT III

000 Rio Brazos Rd., Aztec, Nm 87410

API NO. (assigned by OCD on New Wells)

30-025-23939

5. Indicate Type of Lease

STATE ☒

FEE ☐

6. State Oil & Gas Lease No.

N/A

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

7. Lease Name or Unit Agreement Name

ARROWHEAD GRAYBURG UNIT

1. Type of Well:

OIL ☐ GAS ☐
WELL ☒ WELL ☐ OTHER ☐

2. Name of Operator

CHEVRON U.S.A. INC.

8. Well No.

115

3. Address of Operator

P.O. BOX 1150 MIDLAND, TX 79702 ATTN: NITA RICE

9. Pool name or Wildcat

ARROWHEAD GRAYBURG

4. Well Location

Unit Letter O : 660 Feet From The SOUTH Line and 1650 Feet From The EAST Line
Section 25 Township 21S Range 36E NMPM LEA County

10. Elevation(Show whether DF, RKB, RT, GR, etc.)

3525.3' GL

1 Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
WELL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTER CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABAN. ☐
CASING TEST AND CMT JOB ☐
OTHER: PB F/BLINEBRY TO GRAYBURG ☒

2. Describe Proposed or Completed Operations(Clearly state all pertinent details, and give pertinent dates, including
anticipated date of starting any proposed work) SEE RULE 1103.

WORK STARTED 06/27/94. MIRU. RUN GR LOG. SET CIBP @5490' W/20' CMT ON TOP.
SET CIBP @5160' W/20' CMT ON TOP. SET CIGR @3860'. PUMP 100 SX CL C. POH W/
CIGR. PUMP 22 BFW. PUMP 100 SX PREMIUM PLUS. DRILL TO 2818', FELL THRU TO 3007'.
DRILL TO 3164' FELL THRU TO 3860'. PERF F/3686'-3689'. BREAK DOWN W/4 BBLS HCL.
SPOT 9.5 SX FRAC SD F/3858' TO CIBP. FRAC PERFS W/10,000 GALS 40# X-LINKED
GEL & 20,000 LBS 20/40 BRADY SD & 8000 LBS 20/40 RESIN SD. CLEAN OUT.
END BOP, NU WH. TURN WELL OVER TO PRODUCTION 07/11/94.

I hereby certify that the information above is true and accurate to the best of my knowledge and belief.

SIGNATURE Wendi Kingston TITLE TECH. ASSISTANT

DATE: 08/04/94

TYPE OR PRINT NAME WENDI KINGSTON

TELEPHONE NO. (915)687-7436

ORIGINAL SIGNED BY JERRY SEXTON

APPROVED BY _____ TITLE DISTRICT I SUPERVISOR

DATE AUG 08 1994

CONDITIONS OF APPROVAL, IF ANY: