

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department
OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

Form C-103
Revised 1-1-89

DISTRICT I

P.O. Box 1980, Hobbs, NM 88240

DISTRICT II

P.O. Drawer Dd, Artesia, NM 88210

DISTRICT III

1000 Rio Brazos Rd., Aztec, Nm 87410

API NO. (assigned by OCD on New Wells) 30-025-23949	
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>	
6. State Oil & Gas Lease No. N/A	
7. Lease Name or Unit Agreement Name ARROWHEAD GRAYBURG UNIT	
8. Well No. 108	
9. Pool name or Wildcat ARROWHEAD GRAYBURG	

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	
2. Name of Operator CHEVRON U.S.A. INC.	
3. Address of Operator P.O. BOX 1150 MIDLAND, TX 79702 ATTN: NITA RICE	
4. Well Location Unit Letter I : 2310 Feet From The SOUTH Line and 800 Feet From The EAST Line Section 25 Township 21 SOUTH Range 36E NMPM LEA County	
10. Elevation(Show whether DF, RKB, RT, GR, etc.) 3526'	

11 Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data			
NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTER CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABAN. <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>		CASING TEST AND CMT JOB <input type="checkbox"/>	
OTHER: C/O,ADD PERFS,ACDZ <input type="checkbox"/>		OTHER: <input checked="" type="checkbox"/>	

12. Describe Proposed or Completed Operations(Clearly state all pertinent details, and give pertinent dates, including anticipated date of starting any proposed work) SEE RULE 1103.

WORK STARTED 10/17/94. MIRU, ND WH, NU BOP. PERF F/3688'-3872'.
ACDZ PERFS W/2 BBLs ACID EACH SET. SWAB. ND BOP, NU WH.
TURN WELL OVER TO PRODUCTION 10/20/94.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE  TITLE **TECH. ASSISTANT**

TYPE OR PRINT NAME **WENDI KINGSTON**

DATE: **11/14/94**

TELEPHONE NO. **(915)687-7826**

APPROVED BY **Paul Kautz**
Geologist

TITLE

DATE **NOV 16 1994**

CONDITIONS OF APPROVAL, IF ANY: