

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department
OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

Form C-103
Revised 1-1-89

DISTRICT I

P.O. Box 1980, Hobbs, NM 88240

DISTRICT II

P.O. Drawer Dd, Artesia, NM 88210

DISTRICT III

1000 Rio Brazos Rd., Aztec, Nm 87410

CORRECTED COPY

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		API NO. (assigned by OCD on New Wells) 30-025-241869	
		6. Indicate Type of Lease STATE ☒ FEE ☐	
		6. State Oil & Gas Lease No. N/A	
		7. Lease Name or Unit Agreement Name ARROWHEAD GRAYBURG UNIT	
1. Type of Well: OIL ☒ GAS ☐ WELL ☒ WELL ☐ OTHER ☐		8. Well No. 114	
2. Name of Operator CHEVRON U.S.A. INC.		9. Pool name or Wildcat ARROWHEAD/GB	
3. Address of Operator P.O. BOX 1150 MIDLAND, TX 79702 ATTN: NITA RICE			
4. Well Location Unit Letter <u>N</u> : <u>660</u> Feet From The <u>SOUTH</u> Line and <u>2310</u> Feet From The <u>WEST</u> Line Section <u>25</u> Township <u>21S</u> Range <u>36E</u> NMPM <u>LEA</u> County		10. Elevation(Show whether DF, RKB, RT, GR, etc.) 3520 GL	

11 Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data			
NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☐	REMEDIAL WORK ☐	ALTER CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPNS. ☐	PLUG AND ABAN. ☐
PULL OR ALTER CASING ☐		CASING TEST AND CMT JOB ☐	
OTHER: ☐		OTHER: <u>PLUG BACK & COMPLETE IN ARROWHEAD</u> ☒	

12. Describe Proposed or Completed Operations(Clearly state all pertinent details, and give pertinent dates, including
estimated date of starting any proposed work) SEE RULE 1103.

MIRU , SPOT CMT PLUG FROM 5250-5100 & 4176-3900'. TST CSG FOR 30 MIN TO 600 PSI, OK.
PERF 3910-3913 W/4" CSG GUNS, 4 JHPF. SET CIBP @ 3898. PERF 3864-74 W/20 HOLES, PERF 3852-56
WITH 8 HOLES. ACDZ W/ 15% NEFE HCL. SWAB BACK ACID. PERF 3831-3688 144 HOLES. ACDZ & SWB
BACK ACID. TIH W/TBG & RODS. PBTD 3898'. WORK 8-18 THRU 8-25-92.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.			
SIGNATURE <u>Nita Rice</u>	TITLE <u>TECH. ASSISTANT</u>	DATE: <u>09/22/92</u>	
TYPE OR PRINT NAME <u>NITA RICE</u>		TELEPHONE NO. <u>(915)687-7436</u>	
Orig. Signed <u>Paul Kautz</u> <u>Geologist</u>		DATE <u>SEP 25 '92</u>	
APPROVED BY		DATE	
CONDITIONS OF APPROVAL, IF ANY:			

Abandon Blinby