N.M. OILC JE. I Million

Form 3160-5 (JUNE 1990)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

20. Hox 1980 Hobbs, NM 88241

FORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 31, 1993

Lease Designation and Serial No.
 NM-14791

SUNDRY	NOTICES AND	REPORTS	ON	WELLS
	1 . 1			

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.

Use "APPLICATION FOR PERMIT—" for such proposals

6. If Indian, Allottee or Tribe Name

SUBMIT IN TRIPLICATE	7. If Unit or CA, Agreement Designation 8. Well Name and No. New Mexico A Federal #1 9. API Well No.		
I. Type of Well Oil Gas Well Well X Other Plug and Abandon			
2. Name of Operator STRATA PRODUCTION COMPANY			
3. Address and Telephone No. P. O. Box 1030 505-622-1127 Roswell, New Mexico 88202-1030	30-025-24374 10. Field and Pool, or Exploratory Area		
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)	Hat Mesa Delaware		
1683' FNL & 1650' FWL Section 4-21S-32E	11. County or Parish, State Lea County, New Mexico		
CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, RE	PORT OR OTHER DATA		

2. CHECK APPHOPRIATE BOX(S) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

T	PE OF SUBMISSION			TYPE OF ACTION		,
X	Notice of Intent	-X]	Abandonment			Change of Plans
			Recompletion			New Construction
	Subsequent Report		Plugging Back			Non-Routine Fracturing
			Casing Repair			Water Shut-Off
	Final Abandonment Notice	===	Altering Casing			Conversion to Injection
			OTHER			Dispose Water
					(Note: I Compl	Report results of multiple completion on Well-

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Pursuant to Notice of Incidents of Noncompliance #AJM-045-98 dated 4/29/98, Strata Production Company proposes to plug and abandon the well in the following manner:

- 1. Set CIBP at 6700'. Place 35' of cement on top. Circulate hole with 9.5# per gallon mud.
- 2. Set First Plug at 3300'-3400' with 50 sacks Class "C" cement.
- 3. Set Second Plug at 1350'-1450' with 50 sacks Class "C" cement.
- 4. Set Third Plug at 350'-450' with 50 sacks Class "C" cement.
- 5. Set Surface Plug with 20 sacks Class "C" cement. Spot 9.5# per gallon mud between each plug.
- 6. Cut off wellhead, clean location and reclaim surface.

14. I hereby cedify that the foregoing is true and correct Signed (12.0)		Dunal valies Dans vil 14		
		Production Records Manager	Date	6/1/98
(This space for Federal or State office use) Approved by (ORIG. SGD.) ALEXIS C. SWOBODA Conditions of approval, if any:	Γitle_	PETHOL or LAGUERE	Date	19 1

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

