| STATE OF NEW MEXICO<br>SRGY AND MINERALS DEPARTMENT  |                                       |
|--|---------------------------------------|
| C _ CONSERVATION   | DIVISION                              |
|  |                                       |
| F. O. BOX 2088   | Form C-103<br>Revised 19-1-7:         |
| SANTA FE, NEW MEXIC  | O 87501                               |
| U.S.G.S.   | Sa. Indicate Type of Lease            |
| LAND OFFICE  | State Foo                             |
| OPERATOR .   | 5. State Off & Gas Lease No.          |
|  | Federal                               |
| STINDRY NOTICES AND DEDOCTE ON WELL O  | - There at                            |
| SUNDRY NOTICES AND REPORTS ON WELLS TO BAILL ON TO DEEPEN OF PLUG BACK TO A OF USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSAL   | FFERCHT RESERVOIR.                    |
|  | 7. Unit Agreement Name                |
| TELL OTHER- Injector   | Eunice Monument South U               |
| me of Operator   | 8. Farm or Lease Name                 |
| Chevron U.S.A. Inc.  | · · · · · · · · · · · · · · · · · · · |
| dress at Operator  | 9. Well No.                           |
| P.O. Box 670 Hobbs, NM 88240   | 285                                   |
| cation of Well   | 10. Field and Pool, or Wildcat        |
| UNIT LETTER D 990 PEET PROM THE NORth LINE AND   | 220                                   |
| UNIT CELLER LINE AND   | Eunice Monument G/SA                  |
| West LINE, SECTION 8 TOWNSHIP 218  | 36E (1)                               |
| THE TOWNSHIP RANG  | E                                     |
| THE STATE OF THE S |                                       |
| 15. Elevation (Show whether DF, RT, GF 3572 GL   | 12. County Lea                        |
| Charleston D. T. J. J.   |                                       |
| Check Appropriate Box To Indicate Nature of  | Notice, Report or Other Data          |
| NOTICE OF INTENTION TO:  | SUBSEQUENT REPORT OF:                 |
|  |                                       |

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed pork) SEE RULE 1103.

Clean out to PBTD 0 3966'. Add additional Grayburg perforations from 3702'-3959'. Acidize as necessary. Equip for injection. Test casing, packer, and tubing to 500 psi for 30 minutes. Return to production as an injector.

Convert to Injector

| nereby certify that the information above by frue and completely of the Bulley of | te to the best of my knowledge and belief.  Division Drilling Manager | 9-16-1986        |
|---|---|------------------|
| ORIGINAL SIGNED BY JERRY SEKTON<br>DISTRICT I SUPERVISOR                          |   | 0.00             |
| ITIONS OF ARRESTANCE  | TITLE   | ••• SEP 1 8 1986 |