	orm 9-331 May 1963)						Form approved. Budget Bureau No. 42R1424. 5. LEASE DESIGNATION AND SERIAL NO.		
	GEL JGICAL SURVEY						N1-0362177		
_	SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals.)						6. IF INDIAN, ALLOTTEE OR TRIBE NAME		
ī.	OIL GAS WELL OTHER						7. UNIT AGREEMENT NAME		
2.	NAME OF OPERATOR						8. FARM OR LEASE NAME		
		The Superior Oil Company					Government "H" Com		
3.	D O Dov 1000						9. WELL NO.		
4.	P. O. Box 1900, Midland, Texas 79701 LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*] 10. FIELD AND P	OOL, OR WILDCAT	
	See also space 17 below.) At surface							Undesignated Hat Mesa	
	1980' FML & 1980' FEL, Section 10, T-21-S, R-32-E						11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA		
1	4. PERMIT NO.	15 FLEVATIONS (Sh	CLEVATIONS (Show whether DF, RT, GR, etc.)			<u> </u>	-S, R-32-E		
1	4. FERMII NO.								
	o		RKB: 3800		CL: 3783'		Lea	New Mexico	
16	Check Appropriate Box To Indicate Nature of Notice, Report, or O						her Data		
	NOTICE OF INTENTION TO:					SUBSEQUE	NT REPORT OF:	T REPORT OF:	
	TEST WATER SHUT-OFF		ULL OR ALTER CASING	*	WATER SHUT-OFF	<u>X</u>		IRING WELL	
	FRACTURE TREAT Shoot or acidize		ULTIPLE COMPLETE BANDON*		FRACTURE TREATMES SHOOTING OR ACIDIZ			NING CASING	
	REPAIR WELL		HANGE PLANS		(Other)				
_	(Other) (Note: Report results Completion or Recomplet								
17	 DESCRIBE PROPOSED OR CO proposed work. If w nent to this work.) * 	OMPLETED OPER ell is direction	ATIONS (Clearly state ally drilled, give sul	e all pertinent det bsuriace locations	ills, and give pertiner and measured and tru	nt dates, i 1e vertical	ncluding estimat depths for all n	ed date of starting any markers and zones perti-	
1/4 lb, at 12:2 & cmtd Gilson: at 7:19 Instal to 5000 outside Ran in out cer Tested 5467' f	in hole. Cement /sk celloflake & 35 P.M., 1-19-74 thru DV Tool w/ ite followed by 5 P.M., 1-19-74. led casing head 0 psi, Hydril to e 10-3/4" casing hole with 9-1/2 ment and DV Tool 10-3/4" casing to casing shoe a rs. Now drillin	<pre>2 5 1b/sk 2. Opene 21450 sax 100 sax 2. tested 3500 ps 3. 2. bit. 2. at 3380 to 2000 at 5600'.</pre>	Gilsonite f d DV Tool at Trinity Lit class "C" w/ to 2500 psi i. Ran B-J Tagged top o '. Ran bit psi for 30 m Drilled ou	ollowed by 3380' & c: ewate w/2% 2% CaCl. (. Installe Temperature f cement at to top ceme inutes with	300 sax clas rc out 93 sa: CaCl, 1/4 lb Closed DV Too ed BOP & testo Survey, four 3363' insident at 5467' no pressure	s "C" x cmt. /sk ce 1 w/FP ed BOP nd top e 10-3 inside loss.	<pre>w/2% CaCl. Girculat lloflake & 3000 psi, rams & ch of cement /4" casing 10-3/4" c Cleaned</pre>	Completed ted 4-1/2 hrs 5 lb/sk completed noke manifold t at 375' g. Cleaned tasing. out cement	
						۰,			
								·. ·	
18	8. I hereby certify that	e foregandis	true and correct						
	SIGNED .	blu	T.D. Clay	ritle <u>Pet</u> i	oleum Engine	er	DATE	1-24-74	
	(This space for Federal	or State crice		TITLE					
	CONDITIONS OF APPE	ROVAL, IF AN			R		ALK -		
			*See	Instructions on	Reverse Side			•	
					* .				